

Emergency Contact Telephone Number

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.

Manifest Document No.

2. Page 1 of 1

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address

USEPA REGION 5
77 W. JACKSON BLVD.
CHICAGO, ILL.

4. Generator's Phone (312) 886-7182

JEFFERSON PROCESSING
4243 COUNTY RD. 74
MINGO JCT., OH.

43438

5. Transporter 1 Company Name

ENVIRONMENTAL

6. US EPA ID Number

0-11-D-9-8-7-0-5-1-5-6-4

7. Transporter 2 Company Name

8. US EPA ID Number

9. Designated Facility Name and Site Address

ENVIRONMENTAL PROTECTION SVCS, INC.
4 INDUSTRIAL PARK DRIVE
WHEELING, W.V. 26003

10. US EPA ID Number

0-11-D-9-8-8-7-7-1-6-7-3

A. State Manifest Document Number

B. State Generator's ID

C. State Transporter's ID

D. Transporter's Phone 771-66HW 800-642-1311

E. State Transporter's ID

F. Transporter's Phone

G. State Facility's ID

H. Facility's Phone

304-1-232-1390

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)

HM

a. Non DOT Regulated Polychlorinated Biphenyls

b. Non DOT Regulated Polychlorinated Biphenyls

c. Non DOT Regulated Polychlorinated Biphenyls

d. Non DOT Regulated Polychlorinated Biphenyls

12. Containers

13. Total Quantity

14. Unit Wt/Vol

15. Special Handling Instructions and Additional Information

11a. C-656340/555/radiators

11b. breather / C-656281/52-A

11c. C-656340, C-656341 + C-657612/55-5, 55-6, 55-7 (656340-55-5)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name

Signature

Month Day Year

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

Month Day Year

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

Month Day Year

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 1:

Printed/Typed Name

Signature

Month Day Year

EPA Region 5 Records Ctr.



388236

Please print or type
(Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST

Manifest
Document No.

2. Page 1
of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
USEPA REGION 5
77 W. JACKSON BLVD.
CHICAGO ILL.

4. Generator's Phone (312) 886-7182

5. Transporter 1 Company Name

7. Transporter 2 Company Name Enviroserve

9. Designated Facility Name and Site Address 10
ENVIRONMENTAL PROTECTION SVCS, INC.
4 INDUSTRIAL PARK DRIVE
WHEELING, W.V. 26003

10.	US EPA ID Number
-----	------------------

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)

12. Containers

13.
Total
Quantity

14. Unit
Wt/Vol

I.
Waste No.

a.	Non DOT Regulated Polychlorinated Biphenyls
----	---------------------------------------------

b.	non DOT regulated Polychlorinated Biphenyls
----	---------------------------------------------

c.	Non DDT Regulated Polychlorinated Biphenyls
----	---------------------------------------------

d. Non DOT Regulated Polychlorinated Biphenyls

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above

Date taken out of service - 8/26/00
E.R.G. #171, Energy Cont. 1-800-642-131

15. Special Handling Instructions and Additional Information

11a. C-656340/58/5/radiators

110. breather K-856281/J2-Q

11c. C-656340, C-656341 + C-657612 / SS-J, SS-K, + SS-L (bushings, etc)

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; **OR**, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name

Signature

Month Day Year

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

Month Day Year

18. **Transporter 2 Acknowledgement of Receipt of Materials**

Printed/Typed Name

Signature

Month Day Year

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name

Signature _____

Month Day Year

UNIFORM HAZARDOUS WASTE MANIFEST AND INSTRUCTIONS EPA FORM 8700-22

U.S. EPA Form 8700-22

Read all instructions before completing this form.

This form has been designed for use on a 12-pitch (elite) typewriter; a firm point pen may also be used - press down hard.

Federal regulations require generators and transporters of hazardous waste and owners or operators of hazardous waste treatment, storage, and disposal facilities to use this form (8700-22) and, if necessary, the continuation sheet (Form 8700-22A) for both inter- and intrastate transportation.

Federal regulations also require generators and transporters of hazardous waste and owners or operators of hazardous waste treatment, storage and disposal facilities to complete the following information:

GENERATORS

Item 1. Generator's U.S. EPA ID Number - Manifest Document Number

Enter the generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this Manifest (e.g., 00001) by the generator.

Item 2. Page 1 of -

Enter the total number of pages used to complete this Manifest, i.e., the first page (EPA Form 8700-22) plus the number of Continuation Sheets (EPA Form 8700-22A), if any.

Item 3. Generator's Name and Mailing Address

Enter the name and mailing address of the generator. The address should be the location that will manage the returned Manifest forms.

Item 4. Generator's Phone Number

Enter a telephone number where an authorized agent of the generator may be reached in the event of an emergency.

Item 5. Transporter 1 Company Name

Enter the company name of the first transporter who will transport the waste.

Item 6. U.S. EPA ID Number

Enter the U.S. EPA twelve digit identification number of the first transporter identified in item 5.

Item 7. Transporter 2 Company Name

If applicable, enter the company name of the second transporter who will transport the waste. If more than two transporters are used to transport the waste, use a Continuation Sheet(s) (EPA Form 8700-22A) and list the transporters in the order they will be transporting the waste.

Item 8. U.S. EPA ID Number

If applicable, enter the U.S. EPA twelve digit identification number of the second transporter identified in item 7.

Note.-If more than two transporters are used, enter each additional transporter's company name and U.S. EPA twelve digit identification number in items 24-27 on the Continuation Sheet (EPA Form 8700-22A). Each Continuation Sheet has space to record two additional transporters. Every transporter used between the generator and the designated facility must be listed.

Item 9. Designated Facility Name and Site Address

Enter the company name and site address of the facility designated to receive the waste listed on this Manifest. The address must be the site address, which may differ from the company mailing address.

Item 10. U.S. EPA ID Number

Enter the U.S. EPA twelve digit identification number of the designated facility identified in item 9.

Item 11. U.S. DOT Description [Including Proper Shipping Name, Hazard Class, and ID Number (UN/NA)]

Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste as identified in 49 CFR 171 through 177.

Note.-If additional space is needed for waste descriptions, enter these additional descriptions in item 28 on the Continuation Sheet (EPA Form 8700-22A).

Item 12. Containers (No. and Type)

Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.

Table I - Types of Containers

DM = Metal drums, barrels, kegs	CY = Cylinders
DW = Wooden drums, barrels, kegs	CM = Metal boxes, cartons, cases (including roll-offs)
DF = Fiberboard or plastic drums, barrels, kegs	CW = Wooden boxes, cartons, cases
TP = Tanks portable	CF = Fiber or plastic boxes, cartons, cases
TT = Cargo tanks (tank trucks)	BA = Burlap, cloth, paper or plastic bags
TC = Tank cars	
DT = Dump truck	

Item 13. Total Quantity

Enter the total quantity of waste described on each line.

Item 14. Unit (Wt./Vol.)

Enter the appropriate abbreviation from Table II (below) for the unit of measure.

Table II - Units of Measure

G = Gallons (liquids only)	L = Liters (liquids only)
P = Pounds	K = Kilograms
T = Tons (2000 lbs)	M = Metric tons (1000 kg)
Y = Cubic yards	N = Cubic meters

Item 15. Special Handling Instructions and Additional Information

Generators may use this space to indicate special transportation, treatment, storage, or disposal information or Bill of Lading information. States may not require additional, new, or different information in this space. For international shipments, generators must

enter in this space the point of departure (City and State) for those shipments destined for treatment, storage, or disposal outside the jurisdiction of the United States.

Item 16. Generator's Certification

The generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below. If another mode in addition to the highway mode is used, enter the appropriate additional mode (e.g., and rail) in the space below.

Primary exporters shipping hazardous wastes to a facility located outside of the United States must add to the end of the first sentence of the certification the following words "and conforms to the terms of the EPA Acknowledgment of Consent to the shipment."

In signing the waste minimization certification statement, those generators who have not been exempted by statute or regulation from the duty to make a waste minimization certification under section 3002(b) of RCRA are also certifying that they have complied with the waste minimization requirements.

Generators may preprint the words, "On behalf of" in the signature block or may hand write this statement on the signature block prior to signing the generator certifications.

Note.-All of the above information except the handwritten signature required in item 16 may be preprinted.

TRANSPORTERS

Item 17. Transporter 1 Acknowledgement of Receipt of Materials

Enter the name of the person accepting the waste on behalf of the first transporter. That person must acknowledge acceptance of the waste described on the Manifest by signing and entering the date of receipt.

Item 18. Transporter 2 Acknowledgement of Receipt of Materials

Enter, if applicable, the name of the person accepting the waste on behalf of the second transporter. That person must acknowledge acceptance of the waste described on the Manifest by signing and entering the date of receipt.

Note.-International Shipments - Transporter Responsibilities.

Exports-Transporters must sign and enter the date the waste left the United States in item 15 of Form 8700-22.

Imports-Shipments of hazardous waste regulated by RCRA and transported into the United States from another country must upon entry be accompanied by the U.S. EPA Uniform Hazardous Waste Manifest. Transporters who transport hazardous waste into the United States from another country are responsible for completing the Manifest (40 CFR 263.10(c)(1)).

OWNERS AND OPERATORS OF TREATMENT, STORAGE, OR DISPOSAL FACILITIES

Item 19. Discrepancy Indication Space

The authorized representative of the designated (or alternate) facility's owner or operator must note in this space any significant discrepancy between the waste described on the Manifest and the waste actually received at the facility.

Owners and operators of facilities located in unauthorized States (i.e., the U.S. EPA administers the hazardous waste management program) who cannot resolve significant discrepancies within 15 days of receiving the waste must submit to their Regional Administrator (see list below) a letter with a copy of the Manifest at issue describing the discrepancy and attempts to reconcile it (40 CFR 264.72 and 265.72).

Owners and operators of facilities located in authorized States (i.e., those States that have received authorization from the U.S. EPA to administer the hazardous waste program) should contact their State agency for information on State Discrepancy Report requirements.

EPA Regional Administrators

Regional Administrator, U.S. EPA Region I, J.F. Kennedy Fed. Bldg., Boston, MA 02203

Regional Administrator, U.S. EPA Region II, 26 Federal Plaza, New York, NY 10278

Regional Administrator, U.S. EPA Region III, 6th and Walnut Sts., Philadelphia, PA 19106

Regional Administrator, U.S. EPA Region IV, 345 Courtland St., NE., Atlanta, GA 30365

Regional Administrator, U.S. EPA Region V, 230 S. Dearborn St., Chicago, IL 60604

Regional Administrator, U.S. EPA Region VI, 1201 Elm Street, Dallas, TX 75270

Regional Administrator, U.S. EPA Region VII, 324 East 11th Street, Kansas City, MO 64106

Regional Administrator, U.S. EPA Region VIII, 1860 Lincoln Street, Denver, CO 80295



Regional Administrator, U.S. EPA Region IX, 215 Freemont Street, San Francisco, CA 94105

Regional Administrator, U.S. EPA Region X, 1200 Sixth Avenue, Seattle, WA 98101

Item 20. Facility Owner or Operator: Certification of Receipt of Hazardous Materials Covered by This Manifest Except as Noted in Item 19

Print or type the name of the person accepting the waste on behalf of the owner or operator of the facility. That person must acknowledge acceptance of the waste described on the Manifest by signing and entering the date of receipt.

Items A-K are not required by Federal regulations for intra- or interstate transportation. However, States may require generators and owners or operators of treatment, storage, or disposal facilities to complete some or all of items A-K as part of State manifest reporting requirements. Generators and owners and operators of treatment, storage, or disposal facilities are advised to contact State officials for guidance on completing the shaded areas of the Manifest.

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. 0-H-S-F-N-D-5-0-8-0-3-8-0-0-0-1-9		Manifest Document No. 43938		2. Page 1 of 1		Information in the shaded areas is not required by Federal law.		
GENERATOR	3. Generator's Name and Mailing Address USEPA REGION 5 77 W. JACKSON BLVD. CHICAGO, ILL. 60604				JEFFERSON PROCESSING 4243 COUNTY RD. 74 MINGO JCT., OH.		A. State Manifest Document Number			
	4. Generator's Phone (312) 886-7182						B. State Generator's ID			
	5. Transporter 1 Company Name Enviroserve				6. US EPA ID Number 0-H-D-9-8-7-0-5-0-5-6-4		C. State Transporter's ID 771664W			
	7. Transporter 2 Company Name				8. US EPA ID Number		D. Transporter's Phone 800-642-1311			
	9. Designated Facility Name and Site Address ENVIRONMENTAL PROTECTION SVCS, INC. 4 INDUSTRIAL PARK DRIVE WHEELING, W.V. 26063				10. US EPA ID Number W.V.D.9-8-8-7-7-0-6-7-3		E. State Transporter's ID			
							F. Transporter's Phone			
							G. State Facility's ID			
							H. Facility's Phone 304-232-1590			
	11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)				12. Containers		13. Total Quantity		14. Unit Wt/Vol	
	a. HM Non DOT Regulated Polychlorinated Biphenyls				No. Type				I. Waste No.	
						0.01 CM 25.545 K				
b.										
c.										
d.										
J. Additional Descriptions for Materials Listed Above						K. Handling Codes for Wastes Listed Above				
Date taken out of service - 8/26/00 E.R.G.#171, 24 hr. Emerg. Contact 1-800-642-1311										
15. Special Handling Instructions and Additional Information 11a. C-656340/SS-T/core										
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.										
Printed/Typed Name Thomas Cook				Signature 				Month Day Year 11/01/2000		
TRANSPORTER	17. Transporter 1 Acknowledgement of Receipt of Materials									
	Printed/Typed Name William Bell				Signature 				Month Day Year 11/01/2000	
	18. Transporter 2 Acknowledgement of Receipt of Materials									
Printed/Typed Name				Signature				Month Day Year		
19. Discrepancy Indication Space										
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.										
Printed/Typed Name				Signature				Month Day Year		

Emergency Contact Telephone Number

Please print or type.
(Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039. Expires 9-30-99

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address USEPA REGION 5 77 W. JACKSON BLVD. CHICAGO, ILL. 60604		JEFFERSON PROCESSING 4243 COUNTY RD. 74 MINGO JCT., OH.		A. State Manifest Document Number		
4. Generator's Phone (312) 886-7182		43938		B. State Generator's ID		
5. Transporter 1 Company Name Enviroserve		6. US EPA ID Number O.H.D.9.8.7.0.5.0.5.6.1		C. State Transporter's ID 771664W		
7. Transporter 2 Company Name		8. US EPA ID Number		D. Transporter's Phone 800-642-1311		
9. Designated Facility Name and Site Address ENVIRONMENTAL PROTECTION SVCS, INC. 4 INDUSTRIAL PARK DRIVE WHEELING, W.V. 26063		10. US EPA ID Number W.V.D.9.8.8.7.7.0.6.7.3		E. State Transporter's ID		
				F. Transporter's Phone		
				G. State Facility's ID		
				H. Facility's Phone 304-232-1590		
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)				12. Containers	13. Total Quantity	14. Unit Wt/Vol
				No.	Type	I. Waste No.
a. HM Non DOT Regulated Polychlorinated Biphenyls				0.01	C.M	2.5.5.4.5 K
b.				.	.	.
c.				.	.	.
d.				.	.	.
J. Additional Descriptions for Materials Listed Above				K. Handling Codes for Wastes Listed Above		
Date taken out of service - 8/26/00 E.R.G.#171, 24 hr. Emerg. Contact 1-800-642-1311						
15. Special Handling Instructions and Additional Information 11a. C-656340/SS-J/core						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.						
Printed/Typed Name Thomas Cook				Signature [Signature]		Month Day Year 11.02.60.0
17. Transporter 1 Acknowledgement of Receipt of Materials						
Printed/Typed Name William Bell				Signature William Bell		Month Day Year 11.02.60.0
18. Transporter 2 Acknowledgement of Receipt of Materials						
Printed/Typed Name				Signature		Month Day Year
19. Discrepancy Indication Space						
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.						
Printed/Typed Name				Signature		Month Day Year

UNIFORM HAZARDOUS WASTE MANIFEST AND INSTRUCTIONS EPA FORM 8700-22

U.S. EPA Form 8700-22

Read all instructions before completing this form.

This form has been designed for use on a 12-pitch (elite) typewriter; a firm point pen may also be used - press down hard.

Federal regulations require generators and transporters of hazardous waste and owners or operators of hazardous waste treatment, storage, and disposal facilities to use this form (8700-22) and, if necessary, the continuation sheet (Form 8700-22A) for both inter- and intrastate transportation.

Federal regulations also require generators and transporters of hazardous waste and owners or operators of hazardous waste treatment, storage and disposal facilities to complete the following information:

GENERATORS

Item 1. Generator's U.S. EPA ID Number - Manifest Document Number

Enter the generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this Manifest (e.g., 00001) by the generator.

Item 2. Page 1 of -

Enter the total number of pages used to complete this Manifest, i.e., the first page (EPA Form 8700-22) plus the number of Continuation Sheets (EPA Form 8700-22A), if any.

Item 3. Generator's Name and Mailing Address

Enter the name and mailing address of the generator. The address should be the location that will manage the returned Manifest forms.

Item 4. Generator's Phone Number

Enter a telephone number where an authorized agent of the generator may be reached in the event of an emergency.

Item 5. Transporter 1 Company Name

Enter the company name of the first transporter who will transport the waste.

Item 6. U.S. EPA ID Number

Enter the U.S. EPA twelve digit identification number of the first transporter identified in item 5.

Item 7. Transporter 2 Company Name

If applicable, enter the company name of the second transporter who will transport the waste. If more than two transporters are used to transport the waste, use a Continuation Sheet(s) (EPA Form 8700-22A) and list the transporters in the order they will be transporting the waste.

Item 8. U.S. EPA ID Number

If applicable, enter the U.S. EPA twelve digit identification number of the second transporter identified in item 7.

Note.-If more than two transporters are used, enter each additional transporter's company name and U.S. EPA twelve digit identification number in items 24-27 on the Continuation Sheet (EPA Form 8700-22A). Each Continuation Sheet has space to record two additional transporters. Every transporter used between the generator and the designated facility must be listed.

Item 9. Designated Facility Name and Site Address

Enter the company name and site address of the facility designated to receive the waste listed on this Manifest. The address must be the site address, which may differ from the company mailing address.

Item 10. U.S. EPA ID Number

Enter the U.S. EPA twelve digit identification number of the designated facility identified in item 9.

Item 11. U.S. DOT Description [Including Proper Shipping Name, Hazard Class, and ID Number (UN/NA)]

Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste as identified in 49 CFR 171 through 177.

Note.-If additional space is needed for waste descriptions, enter these additional descriptions in item 28 on the Continuation Sheet (EPA Form 8700-22A).

Item 12. Containers (No. and Type)

Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.

Table I - Types of Containers

DM = Metal drums, barrels, kegs	CY = Cylinders
DW = Wooden drums, barrels, kegs	CM = Metal boxes, cartons, cases
DF = Fiberboard or plastic drums, barrels, kegs	(including roll-offs)
TP = Tanks portable	CW = Wooden boxes, cartons, cases
TT = Cargo tanks (tank trucks)	CF = Fiber or plastic boxes, cartons, cases
TC = Tank cars	BA = Burlap, cloth, paper or plastic bags
DT = Dump truck	

Item 13. Total Quantity

Enter the total quantity of waste described on each line.

Item 14. Unit (Wt./Vol.)

Enter the appropriate abbreviation from Table II (below) for the unit of measure.

Table II - Units of Measure

G = Gallons (liquids only)	L = Liters (liquids only)
P = Pounds	K = Kilograms
T = Tons (2000 lbs)	M = Metric tons (1000 kg)
Y = Cubic yards	N = Cubic meters

Item 15. Special Handling Instructions and Additional Information

Generators may use this space to indicate special transportation, treatment, storage, or disposal information or Bill of Lading information. States may not require additional, new, or different information in this space. For international shipments, generators must

enter in this space the point of departure (City and State) for those shipments destined for treatment, storage, or disposal outside the jurisdiction of the United States.

Item 16. Generator's Certification

The generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below. If another mode in addition to the highway mode is used, enter the appropriate additional mode (e.g., and rail) in the space below.

Primary exporters shipping hazardous wastes to a facility located outside of the United States must add to the end of the first sentence of the certification the following words "and conforms to the terms of the EPA Acknowledgment of Consent to the shipment."

In signing the waste minimization certification statement, those generators who have not been exempted by statute or regulation from the duty to make a waste minimization certification under section 3002(b) of RCRA are also certifying that they have complied with the waste minimization requirements.

Generators may preprint the words, "On behalf of" in the signature block or may hand write this statement on the signature block prior to signing the generator certifications.

Note.-All of the above information except the handwritten signature required in item 16 may be preprinted.

TRANSPORTERS

Item 17. Transporter 1 Acknowledgement of Receipt of Materials

Enter the name of the person accepting the waste on behalf of the first transporter. That person must acknowledge acceptance of the waste described on the Manifest by signing and entering the date of receipt.

Item 18. Transporter 2 Acknowledgement of Receipt of Materials

Enter, if applicable, the name of the person accepting the waste on behalf of the second transporter. That person must acknowledge acceptance of the waste described on the Manifest by signing and entering the date of receipt.

Note.-International Shipments - Transporter Responsibilities.

Exports-Transporters must sign and enter the date the waste left the United States in item 15 of Form 8700-22.

Imports-Shipments of hazardous waste regulated by RCRA and transported into the United States from another country must upon entry be accompanied by the U.S. EPA Uniform Hazardous Waste Manifest. Transporters who transport hazardous waste into the United States from another country are responsible for completing the Manifest (40 CFR 263.10(c)(1)).

OWNERS AND OPERATORS OF TREATMENT, STORAGE, OR DISPOSAL FACILITIES

Item 19. Discrepancy Indication Space

The authorized representative of the designated (or alternate) facility's owner or operator must note in this space any significant discrepancy between the waste described on the Manifest and the waste actually received at the facility.

Owners and operators of facilities located in unauthorized States (i.e., the U.S. EPA administers the hazardous waste management program) who cannot resolve significant discrepancies within 15 days of receiving the waste must submit to their Regional Administrator (see list below) a letter with a copy of the Manifest at issue describing the discrepancy and attempts to reconcile it (40 CFR 264.72 and 265.72).

Owners and operators of facilities located in authorized States (i.e., those States that have received authorization from the U.S. EPA to administer the hazardous waste program) should contact their State agency for information on State Discrepancy Report requirements.

EPA Regional Administrators

Regional Administrator, U.S. EPA Region I, J.F. Kennedy Fed. Bldg., Boston, MA 02203

Regional Administrator, U.S. EPA Region II, 26 Federal Plaza, New York, NY 10278

Regional Administrator, U.S. EPA Region III, 6th and Walnut Sts., Philadelphia, PA 19106

Regional Administrator, U.S. EPA Region IV, 345 Courtland St., NE., Atlanta, GA 30365

Regional Administrator, U.S. EPA Region V, 230 S. Dearborn St., Chicago, IL 60604

Regional Administrator, U.S. EPA Region VI, 1201 Elm Street, Dallas, TX 75270

Regional Administrator, U.S. EPA Region VII, 324 East 11th Street, Kansas City, MO 64106

Regional Administrator, U.S. EPA Region VIII, 1860 Lincoln Street, Denver, CO 80295

Regional Administrator, U.S. EPA Region IX, 215 Fremont Street, San Francisco, CA 94105

Regional Administrator, U.S. EPA Region X, 1200 Sixth Avenue, Seattle, WA 98101

Item 20. Facility Owner or Operator: Certification of Receipt of Hazardous Materials Covered by This Manifest Except as Noted in Item 19

Print or type the name of the person accepting the waste on behalf of the owner or operator of the facility. That person must acknowledge acceptance of the waste described on the Manifest by signing and entering the date of receipt.

Items A-K are not required by Federal regulations for intra- or interstate transportation. However, States may require generators and owners or operators of treatment, storage, or disposal facilities to complete some or all of items A-K as part of State manifest reporting requirements. Generators and owners and operators of treatment, storage, or disposal facilities are advised to contact State officials for guidance on completing the shaded areas of the Manifest.

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address USEPA REGION 5 77 W. JACKSON BLVD. CHICAGO, ILL. 60604 4. Generator's Phone (312) 886-7182		JEFFERSON PROCESSING 4243 COUNTY RD. 74 MINGO JCT., OH. 43938		A. State Manifest Document Number		
5. Transporter 1 Company Name Enviroserve		6. US EPA ID Number 0-H-D-9-8-7-0-5-0-5-6-4		C. State Transporter's ID 77160HW		
7. Transporter 2 Company Name		8. US EPA ID Number		D. Transporter's Phone 800-642-1311		
9. Designated Facility Name and Site Address ENVIRONMENTAL PROTECTION SVCS, INC. 4 Industrial Park Drive WHEELING, W.V. 26003		10. US EPA ID Number W.V.D.9-8-8-7-7-0-6-7-3		E. State Transporter's ID		
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers		13. Total Quantity		
a. HM Non DOT Regulated Polychlorinated Biphenyls		No. Type		14. Unit Wt/Vol		
b. Non DOT Regulated Polychlorinated Biphenyls		0.01 C.M.		4,545 K		
c. Non DOT Regulated Polychlorinated Biphenyls		0.01 C.M.		4,545 K		
d. RQ, Polychlorinated Biphenyls, Mixture Class 9, X P6 III UN2315		0.03 D.M.		1.65 G		
J. Additional Descriptions for Materials Listed Above		K. Handling Codes for Wastes Listed Above				
Date taken out of service - 8/26/00 E.R.G. # 171, 24 hr. Emerg. Contact 1800-642-1311						
15. Special Handling Instructions and Additional Information 11 a + b. C-6S6340/SS-J/casings 11 c. C-6S6341/SS-K/1/2 casing 11 d. 50-499/used mineral oil/SS-J + K (transformers)						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.						
Printed/Typed Name Thomas Cook		Signature TH Cook		Month Day Year 11 02 6000		
17. Transporter 1 Acknowledgement of Receipt of Materials						
Printed/Typed Name William Bell		Signature William Bell		Month Day Year 11 02 6000		
18. Transporter 2 Acknowledgement of Receipt of Materials						
Printed/Typed Name		Signature		Month Day Year		
19. Discrepancy Indication Space						
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.						
Printed/Typed Name		Signature		Month Day Year		

Emergency Contact Telephone Number

Please print or type
(Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039. Expires 9-30-99

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. 0-H-S-F-N-D-5-0-8-03-80-0-0-1-8		Manifest Document No. 0-0-0-1-8		2. Page 1 of 1		Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address USEPA REGION 5 77 W. JACKSON BLVD. CHICAGO, ILL. 60604		JEFFERSON PROCESSING 4243 COUNTY RD. 74 MINGO JCT., OH. 43938		A. State Manifest Document Number					
4. Generator's Phone (312) 886-7182				B. State Generator's ID					
5. Transporter 1 Company Name Enviroserve		6. US EPA ID Number 0-H-D-9-8-7-0-5-0-5-6-4		C. State Transporter's ID 77160HW		D. Transporter's Phone 800-642-1311			
7. Transporter 2 Company Name		8. US EPA ID Number		E. State Transporter's ID		F. Transporter's Phone			
9. Designated Facility Name and Site Address ENVIRONMENTAL PROTECTION SVCS, INC. 4 Industrial Park Drive WHEELING, W.V. 26003		10. US EPA ID Number W.V.-D-9-8-8-7-7-0-6-7-3		G. State Facility's ID		H. Facility's Phone 304-232-1590			
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)				12. Containers		13. Total Quantity		14. Unit Wt/Vol	
				No.		Type		I. Waste No.	
a. HM Non DOT Regulated Polychlorinated Biphenyls				0-0-1		C.M.		4,545 K	
b. Non DOT Regulated Polychlorinated Biphenyls				0-0-1		C.M.		4,545 K	
c. Non DOT Regulated Polychlorinated Biphenyls				0-0-1		C.M.		4,545 K	
d. RQ Polychlorinated Biphenyls, Mixture Class 9, X PG III UN2315				0-0-3		D.M.		1,65 G	
J. Additional Descriptions for Materials Listed Above Date taken out of service - 8/26/00 E.R.C. # 171, 24 hr Emergency Contact 1800-642-1311				K. Handling Codes for Wastes Listed Above					
15. Special Handling Instructions and Additional Information 11a+b. C-656340/SS-J 1 casing 11c. C-656341/SS-K 1/2 casing 11d. 50-499/used mineral oil/SS-J+K (transformers)									
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.									
Printed/Typed Name Thomas Cook				Signature T. Cook				Month Day Year 10/26/00	
17. Transporter 1 Acknowledgement of Receipt of Materials									
Printed/Typed Name William Bell				Signature William Bell				Month Day Year 10/26/00	
18. Transporter 2 Acknowledgement of Receipt of Materials									
Printed/Typed Name				Signature				Month Day Year	
19. Discrepancy Indication Space									
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.									
Printed/Typed Name				Signature				Month Day Year	

UNIFORM HAZARDOUS WASTE MANIFEST AND INSTRUCTIONS EPA FORM 8700-22

U.S. EPA Form 8700-22

Read all instructions before completing this form.

This form has been designed for use on a 12-pitch (elite) typewriter; a firm point pen may also be used – press down hard.

Federal regulations require generators and transporters of hazardous waste and owners or operators of hazardous waste treatment, storage, and disposal facilities to use this form (8700-22) and, if necessary, the continuation sheet (Form 8700-22A) for both inter- and intrastate transportation.

Federal regulations also require generators and transporters of hazardous waste and owners or operators of hazardous waste treatment, storage and disposal facilities to complete the following information:

GENERATORS

Item 1. Generator's U.S. EPA ID Number – Manifest Document Number

Enter the generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this Manifest (e.g., 00001) by the generator.

Item 2. Page 1 of –

Enter the total number of pages used to complete this Manifest, i.e., the first page (EPA Form 8700-22) plus the number of Continuation Sheets (EPA Form 8700-22A), if any.

Item 3. Generator's Name and Mailing Address

Enter the name and mailing address of the generator. The address should be the location that will manage the returned Manifest forms.

Item 4. Generator's Phone Number

Enter a telephone number where an authorized agent of the generator may be reached in the event of an emergency.

Item 5. Transporter 1 Company Name

Enter the company name of the first transporter who will transport the waste.

Item 6. U.S. EPA ID Number

Enter the U.S. EPA twelve digit identification number of the first transporter identified in item 5.

Item 7. Transporter 2 Company Name

If applicable, enter the company name of the second transporter who will transport the waste. If more than two transporters are used to transport the waste, use a Continuation Sheet(s) (EPA Form 8700-22A) and list the transporters in the order they will be transporting the waste.

Item 8. U.S. EPA ID Number

If applicable, enter the U.S. EPA twelve digit identification number of the second transporter identified in item 7.

Note.—If more than two transporters are used, enter each additional transporter's company name and U.S. EPA twelve digit identification number in items 24-27 on the Continuation Sheet (EPA Form 8700-22A). Each Continuation Sheet has space to record two additional transporters. Every transporter used between the generator and the designated facility must be listed.

Item 9. Designated Facility Name and Site Address

Enter the company name and site address of the facility designated to receive the waste listed on this Manifest. The address must be the site address, which may differ from the company mailing address.

Item 10. U.S. EPA ID Number

Enter the U.S. EPA twelve digit identification number of the designated facility identified in item 9.

Item 11. U.S. DOT Description [Including Proper Shipping Name, Hazard Class, and ID Number (UN/NA)]

Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste as identified in 49 CFR 171 through 177.

Note.—If additional space is needed for waste descriptions, enter these additional descriptions in item 28 on the Continuation Sheet (EPA Form 8700-22A).

Item 12. Containers (No. and Type)

Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.

Table I – Types of Containers

DM = Metal drums, barrels, kegs	CY = Cylinders
DW = Wooden drums, barrels, kegs	CM = Metal boxes, cartons, cases
DF = Fiberboard or plastic drums, barrels, kegs	(including roll-offs)
TP = Tanks portable	CW = Wooden boxes, cartons, cases
TT = Cargo tanks (tank trucks)	CF = Fiber or plastic boxes, cartons, cases
TC = Tank cars	BA = Burlap, cloth, paper or plastic bags
DT = Dump truck	

Item 13. Total Quantity

Enter the total quantity of waste described on each line.

Item 14. Unit (Wt./Vol.)

Enter the appropriate abbreviation from Table II (below) for the unit of measure.

Table II – Units of Measure

G = Gallons (liquids only)	L = Liters (liquids only)
P = Pounds	K = Kilograms
T = Tons (2000 lbs)	M = Metric tons (1000 kg)
Y = Cubic yards	N = Cubic meters

Item 15. Special Handling Instructions and Additional Information

Generators may use this space to indicate special transportation, treatment, storage, or disposal information or Bill of Lading information. States may not require additional, new, or different information in this space. For international shipments, generators must

enter in this space the point of departure (City and State) for those shipments destined for treatment, storage, or disposal outside the jurisdiction of the United States.

Item 16. Generator's Certification

The generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below. If another mode in addition to the highway mode is used, enter the appropriate additional mode (e.g., and rail) in the space below.

Primary exporters shipping hazardous wastes to a facility located outside of the United States must add to the end of the first sentence of the certification the following words "and conforms to the terms of the EPA Acknowledgment of Consent to the shipment."

In signing the waste minimization certification statement, those generators who have not been exempted by statute or regulation from the duty to make a waste minimization certification under section 3002(b) of RCRA are also certifying that they have complied with the waste minimization requirements.

Generators may preprint the words, "On behalf of" in the signature block or may hand write this statement on the signature block prior to signing the generator certifications.

Note.—All of the above information except the handwritten signature required in item 16 may be preprinted.

TRANSPORTERS

Item 17. Transporter 1 Acknowledgement of Receipt of Materials

Enter the name of the person accepting the waste on behalf of the first transporter. That person must acknowledge acceptance of the waste described on the Manifest by signing and entering the date of receipt.

Item 18. Transporter 2 Acknowledgement of Receipt of Materials

Enter, if applicable, the name of the person accepting the waste on behalf of the second transporter. That person must acknowledge acceptance of the waste described on the Manifest by signing and entering the date of receipt.

Note.—International Shipments – Transporter Responsibilities.

Exports—Transporters must sign and enter the date the waste left the United States in item 15 of Form 8700-22.

Imports—Shipments of hazardous waste regulated by RCRA and transported into the United States from another country must upon entry be accompanied by the U.S. EPA Uniform Hazardous Waste Manifest. Transporters who transport hazardous waste into the United States from another country are responsible for completing the Manifest (40 CFR 263.10(c)(1)).

OWNERS AND OPERATORS OF TREATMENT, STORAGE, OR DISPOSAL FACILITIES

Item 19. Discrepancy Indication Space

The authorized representative of the designated (or alternate) facility's owner or operator must note in this space any significant discrepancy between the waste described on the Manifest and the waste actually received at the facility.

Owners and operators of facilities located in unauthorized States (i.e., the U.S. EPA administers the hazardous waste management program) who cannot resolve significant discrepancies within 15 days of receiving the waste must submit to their Regional Administrator (see list below) a letter with a copy of the Manifest at issue describing the discrepancy and attempts to reconcile it (40 CFR 264.72 and 265.72).

Owners and operators of facilities located in authorized States (i.e., those States that have received authorization from the U.S. EPA to administer the hazardous waste program) should contact their State agency for information on State Discrepancy Report requirements.

EPA Regional Administrators

Regional Administrator, U.S. EPA Region I, J.F. Kennedy Fed. Bldg., Boston, MA 02203

Regional Administrator, U.S. EPA Region II, 26 Federal Plaza, New York, NY 10278

Regional Administrator, U.S. EPA Region III, 6th and Walnut Sts., Philadelphia, PA 19106

Regional Administrator, U.S. EPA Region IV, 345 Courtland St., NE., Atlanta, GA 30365

Regional Administrator, U.S. EPA Region V, 230 S. Dearborn St., Chicago, IL 60604

Regional Administrator, U.S. EPA Region VI, 1201 Elm Street, Dallas, TX 75270

Regional Administrator, U.S. EPA Region VII, 324 East 11th Street, Kansas City, MO 64106

Regional Administrator, U.S. EPA Region VIII, 1860 Lincoln Street, Denver, CO 80295

Regional Administrator, U.S. EPA Region IX, 215 Fremont Street, San Francisco, CA 94105

Regional Administrator, U.S. EPA Region X, 1200 Sixth Avenue, Seattle, WA 98101

Item 20. Facility Owner or Operator: Certification of Receipt of Hazardous Materials Covered by This Manifest Except as Noted in Item 19

Print or type the name of the person accepting the waste on behalf of the owner or operator of the facility. That person must acknowledge acceptance of the waste described on the Manifest by signing and entering the date of receipt.

Items A-K are not required by Federal regulations for intra- or interstate transportation. However, States may require generators and owners or operators of treatment, storage, or disposal facilities to complete some or all of items A-K as part of State manifest reporting requirements. Generators and owners and operators of treatment, storage, or disposal facilities are advised to contact State officials for guidance on completing the shaded areas of the Manifest.

UNIFORM HAZARDOUS
WASTE MANIFEST

1. Generator's US EPA ID No.

04.S.F.N.D.5.08.038

Manifest
Document No.

0.0.0.1.7

2. Page 1
of 1Information in the shaded areas is
not required by Federal law.

3. Generator's Name and Mailing Address

US EPA REGION 5
77 W. JACKSON BLVD.
CHICAGO, ILL. 60604JEFFERSON PROCESSING
4243 COUNTY RD. 74
MINGO JCT., OH.

4. Generator's Phone (312) 886-7182

43938

5. Transporter 1 Company Name

Enviroserve

6. US EPA ID Number

04.D.9.8.7.0.5.0.5.6.4

7. Transporter 2 Company Name

8. US EPA ID Number

.

9. Designated Facility Name and Site Address

ENVIRONMENTAL PROTECTION SVCS., INC.
4 INDUSTRIAL PARK DRIVE
WHEELING, W.V. 26003

10. US EPA ID Number

W.V.D.9.8.8.7.7.0.6.7.3

A. State Manifest Document Number

B. State Generator's ID

C. State Transporter's ID 77160HW

D. Transporter's Phone 800-642-1311

E. State Transporter's ID

F. Transporter's Phone

G. State Facility's ID

H. Facility's Phone

304-232-1590

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)

HM

12. Containers

No.

Type

13. Total
Quantity14. Unit
Wt/VolI.
Waste No.a. ☒ Non DOT Regulated Polychlorinated
Biphenyls

0.2.4 C.M. 9.8.1.8 K

b. ☒ RQ, Polychlorinated Biphenyls, Mixture
Class 9, PG III UN 2315

0.0.4 C.M. 5.4.5 K

c.

d.

J. Additional Descriptions for Materials Listed Above

Date taken out of service - 8/26/00

K. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information

11a C-657612/SS-L/radiators (16)
C-656341/SS-K/radiators (8)

11b. breathers/JI-A, B, C+I (transformers)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name

Thomas Cook

Signature

T. L. Cook

Month Day Year

1/0/26/00

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

MICHAEL E. ERNEST

Signature

Michael E. Ernest

Month Day Year

1/0/26/00

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

Month Day Year

.

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19

Printed/Typed Name

Signature

Month Day Year

.

GENERATOR

TRANSPORTER

FACILITY

Emergency Contact Telephone Number

Please print or type
(Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039. Expires 9-30-99

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. <i>045ENB50803800017</i>		Manifest Document No. <i>43938</i>		2. Page 1 of 1		Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address <i>USEPA REGION 5 77 W. JACKSON BLVD. CHICAGO, ILL. 60604</i>						JEFFERSON PROCESSING 4243 COUNTY RD. 74 MINGO JCT., OH.			
4. Generator's Phone <i>312 886-7182</i>									
5. Transporter 1 Company Name <i>ENVIRONMENTAL PROTECTION SVCS., INC.</i>						6. US EPA ID Number <i>045ENB50803800017</i>			
7. Transporter 2 Company Name						8. US EPA ID Number			
9. Designated Facility Name and Site Address <i>ENVIRONMENTAL PROTECTION SVCS., INC. 4 INDUSTRIAL PARK DRIVE WHEELING, W.V. 26003</i>						10. US EPA ID Number <i>WV0988770673</i>			
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)						12. Containers		13. Total Quantity	
						No. Type		14. Unit Wt/Vol	
a. <i>HM</i> Non DOT Regulated Polychlorinated Biphenyls						<i>674 CM</i>		<i>98.18 K</i>	
b. <i>X</i> RQ, Polychlorinated Biphenyls, mixture Class 9, PG III UN 2315						<i>0.04 CM</i>		<i>54.5 K</i>	
c.									
d.									
J. Additional Descriptions for Materials Listed Above						K. Handling Codes for Wastes Listed Above			
<i>Date taken out of service - 8/26/00</i>									
15. Special Handling Instructions and Additional Information									
<i>11a C-657612/SS-L/radiators (16) C-656341/SS-K/radiators (8) 11b. breathers/JI-A,B,C+I (transformers)</i>									
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.									
Printed/Typed Name <i>Thomas Cook</i>					Signature <i>TL Cook</i>			Month Day Year <i>10 26 00</i>	
17. Transporter 1 Acknowledgement of Receipt of Materials									
Printed/Typed Name <i>MICHAEL E. ERNEST</i>					Signature <i>Michael E. Ernest</i>			Month Day Year <i>10 26 00</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials									
Printed/Typed Name					Signature			Month Day Year	
19. Discrepancy Indication Space									
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.									
Printed/Typed Name					Signature			Month Day Year	

UNIFORM HAZARDOUS WASTE MANIFEST AND INSTRUCTIONS EPA FORM 8700-22

U.S. EPA Form 8700-22

Read all instructions before completing this form.

This form has been designed for use on a 12-pitch (elite) typewriter; a firm point pen may also be used - press down hard.

Federal regulations require generators and transporters of hazardous waste and owners or operators of hazardous waste treatment, storage, and disposal facilities to use this form (8700-22) and, if necessary, the continuation sheet (Form 8700-22A) for both inter- and intrastate transportation.

Federal regulations also require generators and transporters of hazardous waste and owners or operators of hazardous waste treatment, storage and disposal facilities to complete the following information:

GENERATORS

Item 1. Generator's U.S. EPA ID Number - Manifest Document Number

Enter the generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this Manifest (e.g., 00001) by the generator.

Item 2. Page 1 of -

Enter the total number of pages used to complete this Manifest, i.e., the first page (EPA Form 8700-22) plus the number of Continuation Sheets (EPA Form 8700-22A), if any.

Item 3. Generator's Name and Mailing Address

Enter the name and mailing address of the generator. The address should be the location that will manage the returned Manifest forms.

Item 4. Generator's Phone Number

Enter a telephone number where an authorized agent of the generator may be reached in the event of an emergency.

Item 5. Transporter 1 Company Name

Enter the company name of the first transporter who will transport the waste.

Item 6. U.S. EPA ID Number

Enter the U.S. EPA twelve digit identification number of the first transporter identified in item 5.

Item 7. Transporter 2 Company Name

If applicable, enter the company name of the second transporter who will transport the waste. If more than two transporters are used to transport the waste, use a Continuation Sheet(s) (EPA Form 8700-22A) and list the transporters in the order they will be transporting the waste.

Item 8. U.S. EPA ID Number

If applicable, enter the U.S. EPA twelve digit identification number of the second transporter identified in item 7.

Note.-If more than two transporters are used, enter each additional transporter's company name and U.S. EPA twelve digit identification number in items 24-27 on the Continuation Sheet (EPA Form 8700-22A). Each Continuation Sheet has space to record two additional transporters. Every transporter used between the generator and the designated facility must be listed.

Item 9. Designated Facility Name and Site Address

Enter the company name and site address of the facility designated to receive the waste listed on this Manifest. The address must be the site address, which may differ from the company mailing address.

Item 10. U.S. EPA ID Number

Enter the U.S. EPA twelve digit identification number of the designated facility identified in item 9.

Item 11. U.S. DOT Description [Including Proper Shipping Name, Hazard Class, and ID Number (UN/NA)]

Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste as identified in 49 CFR 171 through 177.

Note.-If additional space is needed for waste descriptions, enter these additional descriptions in item 28 on the Continuation Sheet (EPA Form 8700-22A).

Item 12. Containers (No. and Type)

Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.

Table I - Types of Containers

DM = Metal drums, barrels, kegs	CY = Cylinders
DW = Wooden drums, barrels, kegs	KM = Metal boxes, cartons, cases (including roll-offs)
DF = Fiberboard or plastic drums, barrels, kegs	CM = Wooden boxes, cartons, cases
TP = Tanks portable	CF = Fiber or plastic boxes, cartons, cases
TT = Cargo tanks (tank trucks)	BA = Burlap, cloth, paper or plastic bags
TC = Tank cars	
DT = Dump truck	

Item 13. Total Quantity

Enter the total quantity of waste described on each line.

Item 14. Unit (Wt./Vol.)

Enter the appropriate abbreviation from Table II (below) for the unit of measure.

Table II - Units of Measure

G = Gallons (liquids only)	L = Liters (liquids only)
P = Pounds	K = Kilograms
T = Tons (2000 lbs)	M = Metric tons (1000 kg)
Y = Cubic yards	N = Cubic meters

Item 15. Special Handling Instructions and Additional Information

Generators may use this space to indicate special transportation, treatment, storage, or disposal information or Bill of Lading information. States may not require additional, new, or different information in this space. For international shipments, generators must

enter in this space the point of departure (City and State) for those shipments destined for treatment, storage, or disposal outside the jurisdiction of the United States.

Item 16. Generator's Certification

The generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below. If another mode in addition to the highway mode is used, enter the appropriate additional mode (e.g., and rail) in the space below.

Primary exporters shipping hazardous wastes to a facility located outside of the United States must add to the end of the first sentence of the certification the following words "and conforms to the terms of the EPA Acknowledgment of Consent to the shipment."

In signing the waste minimization certification statement, those generators who have not been exempted by statute or regulation from the duty to make a waste minimization certification under section 3002(b) of RCRA are also certifying that they have complied with the waste minimization requirements.

Generators may preprint the words, "On behalf of" in the signature block or may hand write this statement on the signature block prior to signing the generator certifications.

Note.-All of the above information except the handwritten signature required in item 16 may be preprinted.

TRANSPORTERS

Item 17. Transporter 1 Acknowledgement of Receipt of Materials

Enter the name of the person accepting the waste on behalf of the first transporter. That person must acknowledge acceptance of the waste described on the Manifest by signing and entering the date of receipt.

Item 18. Transporter 2 Acknowledgement of Receipt of Materials

Enter, if applicable, the name of the person accepting the waste on behalf of the second transporter. That person must acknowledge acceptance of the waste described on the Manifest by signing and entering the date of receipt.

Note.-International Shipments - Transporter Responsibilities.

Exports-Transporters must sign and enter the date the waste left the United States in item 15 of Form 8700-22.

Imports-Shipments of hazardous waste regulated by RCRA and transported into the United States from another country must upon entry be accompanied by the U.S. EPA Uniform Hazardous Waste Manifest. Transporters who transport hazardous waste into the United States from another country are responsible for completing the Manifest (40 CFR 263.10(c)(1)).

OWNERS AND OPERATORS OF TREATMENT, STORAGE, OR DISPOSAL FACILITIES

Item 19. Discrepancy Indication Space

The authorized representative of the designated (or alternate) facility's owner or operator must note in this space any significant discrepancy between the waste described on the Manifest and the waste actually received at the facility.

Owners and operators of facilities located in unauthorized States (i.e., the U.S. EPA administers the hazardous waste management program) who cannot resolve significant discrepancies within 15 days of receiving the waste must submit to their Regional Administrator (see list below) a letter with a copy of the Manifest at issue describing the discrepancy and attempts to reconcile it (40 CFR 264.72 and 265.72).

Owners and operators of facilities located in authorized States (i.e., those States that have received authorization from the U.S. EPA to administer the hazardous waste program) should contact their State agency for information on State Discrepancy Report requirements.

EPA Regional Administrators

Regional Administrator, U.S. EPA Region I, J.F. Kennedy Fed. Bldg., Boston, MA 02203

Regional Administrator, U.S. EPA Region II, 26 Federal Plaza, New York, NY 10278

Regional Administrator, U.S. EPA Region III, 6th and Walnut Sts., Philadelphia, PA 19106

Regional Administrator, U.S. EPA Region IV, 345 Courtland St., NE., Atlanta, GA 30365

Regional Administrator, U.S. EPA Region V, 230 S. Dearborn St., Chicago, IL 60604

Regional Administrator, U.S. EPA Region VI, 1201 Elm Street, Dallas, TX 75270

Regional Administrator, U.S. EPA Region VII, 324 East 11th Street, Kansas City, MO 64106

Regional Administrator, U.S. EPA Region VIII, 1860 Lincoln Street, Denver, CO 80295


Regional Administrator, U.S. EPA Region IX, 215 Freemont Street, San Francisco, CA 94105

Regional Administrator, U.S. EPA Region X, 1200 Sixth Avenue, Seattle, WA 98101

Item 20. Facility Owner or Operator: Certification of Receipt of Hazardous Materials Covered by This Manifest Except as Noted in Item 19

Print or type the name of the person accepting the waste on behalf of the owner or operator of the facility. That person must acknowledge acceptance of the waste described on the Manifest by signing and entering the date of receipt.

Items A-K are not required by Federal regulations for intra- or interstate transportation. However, States may require generators and owners or operators of treatment, storage, or disposal facilities to complete some or all of items A-K as part of State manifest reporting requirements. Generators and owners and operators of treatment, storage, or disposal facilities are advised to contact State officials for guidance on completing the shaded areas of the Manifest.

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. 045FN0508038000016		Manifest Document No. 00016		2. Page 1 of 1		Information in the shaded areas is not required by Federal law.		
GENERATOR	3. Generator's Name and Mailing Address USEPA REGION 5 77 W. JACKSON BLVD. CHICAGO, ILL. 60604					JEFFERSON PROCESSING 4243 COUNTY RD. 74 MINGO JCT., OH.				
	4. Generator's Phone (312) 886-7182					43938				
	5. Transporter 1 Company Name Enviroserve					6. US EPA ID Number 04D987050564				
	7. Transporter 2 Company Name					8. US EPA ID Number				
	9. Designated Facility Name and Site Address ENVIRONMENTAL PROTECTION SVCS, INC. 4 Industrial Park Drive Wheeling, W.V. 26003					10. US EPA ID Number WV098710673				
	11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)					12. Containers		13. Total Quantity	14. Unit Wt/Vol	15. Waste No.
	a. Non Dot Regulated Polychlorinated Biphenyls					No.	Type			
J. Additional Descriptions for Materials Listed Above Date taken out of service - 8/26/00					K. Handling Codes for Wastes Listed Above					
15. Special Handling Instructions and Additional Information 11a. C-656341 / SS-K/core										
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.										
Printed/Typed Name Thomas Cook					Signature 			Month Day Year 11/02/00		
TRANSPORTER	17. Transporter 1 Acknowledgement of Receipt of Materials					Signature Tom Stanton			Month Day Year 11/02/00	
	18. Transporter 2 Acknowledgement of Receipt of Materials					Signature			Month Day Year	
	Printed/Typed Name									
FACILITY	19. Discrepancy Indication Space									
	20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.									
Printed/Typed Name					Signature			Month Day Year		

Emergency Contact Telephone Number

Please print or type
(Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039. Expires 9-30-99

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. <i>04H5FND50803800016</i>		Manifest Document No. <i>JEFFERSON PROCESSING 4243 COUNTY RD. 74 MINGO JCT., OH.</i>		2. Page 1 of <i>1</i>		Information in the shaded areas is not required by Federal law.																
3. Generator's Name and Mailing Address <i>USEPA REGION 5 77 W. JACKSON BLVD. CHICAGO, ILL. 60604</i>						A. State Manifest Document Number																		
						B. State Generator's ID																		
4. Generator's Phone (<i>312</i>) <i>886-7182</i>						C. State Transporter's ID <i>77160HW</i>																		
5. Transporter 1 Company Name <i>Enviroserve</i>						D. Transporter's Phone <i>800-642-1311</i>																		
7. Transporter 2 Company Name						E. State Transporter's ID																		
8. US EPA ID Number						F. Transporter's Phone																		
9. Designated Facility Name and Site Address <i>ENVIRONMENTAL PROTECTION SVCS, INC. 4 Industrial Park Drive Wheeling, W.V. 26003</i>						G. State Facility's ID																		
10. US EPA ID Number <i>WV-D-98877-0673</i>						H. Facility's Phone <i>304-232-1590</i>																		
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number) <i>HM</i> a. <i>Non Dot Regulated Polychlorinated Biphenyls</i>						12. Containers		13. Total Quantity		14. Unit Wt/Vol		15. Waste No.												
						No.		Type																
						<i>001CM</i>		<i>25545</i>		<i>K</i>														
															
															
J. Additional Descriptions for Materials Listed Above <i>Date taken out of service - 8/26/00</i>						K. Handling Codes for Wastes Listed Above																		
15. Special Handling Instructions and Additional Information <i>Ma. C-656341 / SS-K/core</i>																								
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.																								
Printed/Typed Name <i>Thomas C. L.</i>					Signature <i>Thomas C. L.</i>					Month Day Year <i>11/02/00</i>														
17. Transporter 1 Acknowledgement of Receipt of Materials										Printed/Typed Name <i>Tom Stanton</i>					Signature <i>Tom Stanton</i>					Month Day Year <i>11/02/00</i>				
										18. Transporter 2 Acknowledgement of Receipt of Materials										Printed/Typed Name				
19. Discrepancy Indication Space																				Printed/Typed Name				
										20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.										Printed/Typed Name				
																				Printed/Typed Name				

UNIFORM HAZARDOUS WASTE MANIFEST AND INSTRUCTIONS EPA FORM 8700-22

U.S. EPA Form 8700-22

Read all instructions before completing this form.

This form has been designed for use on a 12-pitch (elite) typewriter; a firm point pen may also be used - press down hard.

Federal regulations require generators and transporters of hazardous waste and owners or operators of hazardous waste treatment, storage, and disposal facilities to use this form (8700-22) and, if necessary, the continuation sheet (Form 8700-22A) for both inter- and intrastate transportation.

Federal regulations also require generators and transporters of hazardous waste and owners or operators of hazardous waste treatment, storage and disposal facilities to complete the following information:

GENERATORS

Item 1. Generator's U.S. EPA ID Number - Manifest Document Number

Enter the generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this Manifest (e.g., 00001) by the generator.

Item 2. Page 1 of -

Enter the total number of pages used to complete this Manifest, i.e., the first page (EPA Form 8700-22) plus the number of Continuation Sheets (EPA Form 8700-22A), if any.

Item 3. Generator's Name and Mailing Address

Enter the name and mailing address of the generator. The address should be the location that will manage the returned Manifest forms.

Item 4. Generator's Phone Number

Enter a telephone number where an authorized agent of the generator may be reached in the event of an emergency.

Item 5. Transporter 1 Company Name

Enter the company name of the first transporter who will transport the waste.

Item 6. U.S. EPA ID Number

Enter the U.S. EPA twelve digit identification number of the first transporter identified in item 5.

Item 7. Transporter 2 Company Name

If applicable, enter the company name of the second transporter who will transport the waste. If more than two transporters are used to transport the waste, use a Continuation Sheet(s) (EPA Form 8700-22A) and list the transporters in the order they will be transporting the waste.

Item 8. U.S. EPA ID Number

If applicable, enter the U.S. EPA twelve digit identification number of the second transporter identified in item 7.

Note.-If more than two transporters are used, enter each additional transporter's company name and U.S. EPA twelve digit identification number in items 24-27 on the Continuation Sheet (EPA Form 8700-22A). Each Continuation Sheet has space to record two additional transporters. Every transporter used between the generator and the designated facility must be listed.

Item 9. Designated Facility Name and Site Address

Enter the company name and site address of the facility designated to receive the waste listed on this Manifest. The address must be the site address, which may differ from the company mailing address.

Item 10. U.S. EPA ID Number

Enter the U.S. EPA twelve digit identification number of the designated facility identified in item 9.

Item 11. U.S. DOT Description [Including Proper Shipping Name, Hazard Class, and ID Number (UN/NA)]

Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste as identified in 49 CFR 171 through 177.

Note.-If additional space is needed for waste descriptions, enter these additional descriptions in item 28 on the Continuation Sheet (EPA Form 8700-22A).

Item 12. Containers (No. and Type)

Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.

Table I - Types of Containers

DM = Metal drums, barrels, kegs	CY = Cylinders
DW = Wooden drums, barrels, kegs	CM = Metal boxes, cartons, cases (including roll-offs)
DF = Fiberboard or plastic drums, barrels, kegs	CW = Wooden boxes, cartons, cases
TP = Tanks portable	CF = Fiber or plastic boxes, cartons, cases
TT = Cargo tanks (tank trucks)	BA = Burlap, cloth, paper or plastic bags
TC = Tank cars	
DT = Dump truck	

Item 13. Total Quantity

Enter the total quantity of waste described on each line.

Item 14. Unit (Wt/Vol.)

Enter the appropriate abbreviation from Table II (below) for the unit of measure.

Table II - Units of Measure

G = Gallons (liquids only)	L = Liters (liquids only)
P = Pounds	K = Kilograms
T = Tons (2000 lbs)	M = Metric tons (1000 kg)
Y = Cubic yards	N = Cubic meters

Item 15. Special Handling Instructions and Additional Information

Generators may use this space to indicate special transportation, treatment, storage, or disposal information or Bill of Lading information. States may not require additional, new, or different information in this space. For international shipments, generators must

enter in this space the point of departure (City and State) for those shipments destined for treatment, storage, or disposal outside the jurisdiction of the United States.

Item 16. Generator's Certification

The generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below. If another mode in addition to the highway mode is used, enter the appropriate additional mode (e.g., and rail) in the space below.

Primary exporters shipping hazardous wastes to a facility located outside of the United States must add to the end of the first sentence of the certification the following words "and conforms to the terms of the EPA Acknowledgment of Consent to the shipment."

In signing the waste minimization certification statement, those generators who have not been exempted by statute or regulation from the duty to make a waste minimization certification under section 3002(b) of RCRA are also certifying that they have complied with the waste minimization requirements.

Generators may preprint the words "On behalf of" in the signature block or may hand write this statement on the signature block prior to signing the generator certifications.

Note.-All of the above information except the handwritten signature required in item 16 may be preprinted.

TRANSPORTERS

Item 17. Transporter 1 Acknowledgement of Receipt of Materials

Enter the name of the person accepting the waste on behalf of the first transporter. That person must acknowledge acceptance of the waste described on the Manifest by signing and entering the date of receipt.

Item 18. Transporter 2 Acknowledgement of Receipt of Materials

Enter, if applicable, the name of the person accepting the waste on behalf of the second transporter. That person must acknowledge acceptance of the waste described on the Manifest by signing and entering the date of receipt.

Note.-International Shipments - Transporter Responsibilities.

Exports-Transporters must sign and enter the date the waste left the United States in item 15 of Form 8700-22.

Imports-Shipments of hazardous waste regulated by RCRA and transported into the United States from another country must upon entry be accompanied by the U.S. EPA Uniform Hazardous Waste Manifest. Transporters who transport hazardous waste into the United States from another country are responsible for completing the Manifest (40 CFR 263.10(c)(1)).

OWNERS AND OPERATORS OF TREATMENT, STORAGE, OR DISPOSAL FACILITIES

Item 19. Discrepancy Indication Space

The authorized representative of the designated (or alternate) facility's owner or operator must note in this space any significant discrepancy between the waste described on the Manifest and the waste actually received at the facility.

Owners and operators of facilities located in unauthorized States (i.e., the U.S. EPA administers the hazardous waste management program) who cannot resolve significant discrepancies within 15 days of receiving the waste must submit to their Regional Administrator (see list below) a letter with a copy of the Manifest at issue describing the discrepancy and attempts to reconcile it (40 CFR 264.72 and 265.72).

Owners and operators of facilities located in authorized States (i.e., those States that have received authorization from the U.S. EPA to administer the hazardous waste program) should contact their State agency for information on State Discrepancy Report requirements.

EPA Regional Administrators

Regional Administrator, U.S. EPA Region I, J.F. Kennedy Fed. Bldg., Boston, MA 02203

Regional Administrator, U.S. EPA Region II, 26 Federal Plaza, New York, NY 10278

Regional Administrator, U.S. EPA Region III, 6th and Walnut Sts., Philadelphia, PA 19106

Regional Administrator, U.S. EPA Region IV, 345 Courtland St., NE., Atlanta, GA 30365

Regional Administrator, U.S. EPA Region V, 230 S. Dearborn St., Chicago, IL 60604

Regional Administrator, U.S. EPA Region VI, 1201 Elm Street, Dallas, TX 75270

Regional Administrator, U.S. EPA Region VII, 324 East 11th Street, Kansas City, MO 64106

Regional Administrator, U.S. EPA Region VIII, 1860 Lincoln Street, Denver, CO 80295

Regional Administrator, U.S. EPA Region IX, 215 Fremont Street, San Francisco, CA 94105

Regional Administrator, U.S. EPA Region X, 1200 Sixth Avenue, Seattle, WA 98101

Item 20. Facility Owner or Operator: Certification of Receipt of Hazardous Materials Covered by This Manifest Except as Noted in Item 19

Print or type the name of the person accepting the waste on behalf of the owner or operator of the facility. That person must acknowledge acceptance of the waste described on the Manifest by signing and entering the date of receipt.

Items A-K are not required by Federal regulations for intra- or interstate transportation. However, States may require generators and owners or operators of treatment, storage, or disposal facilities to complete some or all of items A-K as part of State manifest reporting requirements. Generators and owners and operators of treatment, storage, or disposal facilities are advised to contact State officials for guidance on completing the shaded areas of the Manifest.

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address USEPA REGION 5 77 W. JACKSON BLVD. CHICAGO, ILL. 60604		1. Generator's US EPA ID No. D.H.S.F.N.D.5.0.8.0.3.8		Manifest Document No. D.0.0.1.5		A. State Manifest Document Number
4. Generator's Phone (312) 886-7182		JEFFERSON PROCESSING 4243 COUNTY RD. 74 MINGO JCT, OH. 43938				B. State Generator's ID
5. Transporter 1 Company Name Enviroserve		6. US EPA ID Number 10.H.D.9.8.7.0.5.0.5.6.4		C. State Transporter's ID 77160HW		D. Transporter's Phone 800-642-1311
7. Transporter 2 Company Name		8. US EPA ID Number		E. State Transporter's ID		F. Transporter's Phone
9. Designated Facility Name and Site Address ENVIRONMENTAL PROTECTION SVCS, INC. 4 INDUSTRIAL BLVD. WHEELING, WV. 26003		10. US EPA ID Number W.V.D.9.8.8.7.7.0.6.7.3		G. State Facility's ID		H. Facility's Phone 304-232-1590
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers		13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. <input checked="" type="checkbox"/> Non DOT Regulated Polychlorinated Biphenyls		0.0.1 C.M.		4,545 K		
b. <input checked="" type="checkbox"/> Non DOT Regulated Polychlorinated Biphenyls		0.0.1 C.M.		4,545 K		
c. <input checked="" type="checkbox"/> Non DOT Regulated Polychlorinated Biphenyls		0.0.1 C.M.		4,545 K		
d.						
J. Additional Descriptions for Materials Listed Above Date taken out of service - 8/26/00				K. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information 11a & b C-657612 / SS-L / casing 11c C-656341 / SS-K / 1/2 casing						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.						
Printed/Typed Name Thomas Cook		Signature [Signature]		Month Day Year 11/02/00		
17. Transporter 1 Acknowledgement of Receipt of Materials		Printed/Typed Name Tom Stanton		Signature [Signature]		Month Day Year 11/02/00
18. Transporter 2 Acknowledgement of Receipt of Materials		Printed/Typed Name		Signature		Month Day Year
19. Discrepancy Indication Space						
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.						
Printed/Typed Name		Signature		Month Day Year		

Emergency Contact Telephone Number

Please print or type
(Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039. Expires 9-30-99

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address USEPA REGION 5 77 W. JACKSON Blvd. CHICAGO, ILL. 60604		JEFFERSON PROCESSING 4243 COUNTY RD. 74 MINGO JCT, OH. 43938		A. State Manifest Document Number		
4. Generator's Phone (312) 886-7182				B. State Generator's ID		
5. Transporter 1 Company Name Enviroserve		6. US EPA ID Number O.H.D.9.8.7.0.5.0.5.6.4		C. State Transporter's ID 77160 HW		
7. Transporter 2 Company Name		8. US EPA ID Number		D. Transporter's Phone 800-642-1311		
9. Designated Facility Name and Site Address ENVIRONMENTAL PROTECTION SVCS, INC. 4 INDUSTRIAL BLVD. WHEELING, W.V. 26003		10. US EPA ID Number W.V.D.9.8.8.7.7.0.6.7.3		E. State Transporter's ID		
				F. Transporter's Phone		
				G. State Facility's ID		
				H. Facility's Phone 304-232-1590		
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)				12. Containers	13. Total Quantity	14. Unit Wt/Vol
				No.	Type	I. Waste No.
a.	HM Non DOT Regulated Polychlorinated Biphenyls			0.01 C.M.	4,545 K	
b.	Non DOT Regulated Polychlorinated Biphenyls			0.01 C.M.	4,545 K	
c.	Non DOT Regulated Polychlorinated Biphenyls			0.01 C.M.	4,545 K	
d.						
J. Additional Descriptions for Materials Listed Above Date taken out of service - 8/26/00				K. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information 11a & b C-657612 / SS-L / casing 11c C-656341 / SS-K / 1/2 casing						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.						
Printed/Typed Name Thomas Cook		Signature [Signature]		Month Day Year 11/02/96		
17. Transporter 1 Acknowledgement of Receipt of Materials						
Printed/Typed Name Tom Stanton		Signature Tom Stanton		Month Day Year 11/02/00		
18. Transporter 2 Acknowledgement of Receipt of Materials						
Printed/Typed Name		Signature		Month Day Year		
19. Discrepancy Indication Space						
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.						
Printed/Typed Name		Signature		Month Day Year		

UNIFORM HAZARDOUS WASTE MANIFEST AND INSTRUCTIONS EPA FORM 8700-22

U.S. EPA Form 8700-22

Read all instructions before completing this form.

This form has been designed for use on a 12-pitch (elite) typewriter; a firm point pen may also be used -- press down hard.

Federal regulations require generators and transporters of hazardous waste and owners or operators of hazardous waste treatment, storage, and disposal facilities to use this form (8700-22) and, if necessary, the continuation sheet (Form 8700-22A) for both inter- and intrastate transportation.

Federal regulations also require generators and transporters of hazardous waste and owners or operators of hazardous waste treatment, storage and disposal facilities to complete the following information:

GENERATORS

Item 1. Generator's U.S. EPA ID Number -- Manifest Document Number

Enter the generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this Manifest (e.g., 00001) by the generator.

Item 2. Page 1 of --

Enter the total number of pages used to complete this Manifest, i.e., the first page (EPA Form 8700-22) plus the number of Continuation Sheets (EPA Form 8700-22A), if any.

Item 3. Generator's Name and Mailing Address

Enter the name and mailing address of the generator. The address should be the location that will manage the returned Manifest forms.

Item 4. Generator's Phone Number

Enter a telephone number where an authorized agent of the generator may be reached in the event of an emergency.

Item 5. Transporter 1 Company Name

Enter the company name of the first transporter who will transport the waste.

Item 6. U.S. EPA ID Number

Enter the U.S. EPA twelve digit identification number of the first transporter identified in item 5.

Item 7. Transporter 2 Company Name

If applicable, enter the company name of the second transporter who will transport the waste. If more than two transporters are used to transport the waste, use a Continuation Sheet(s) (EPA Form 8700-22A) and list the transporters in the order they will be transporting the waste.

Item 8. U.S. EPA ID Number

If applicable, enter the U.S. EPA twelve digit identification number of the second transporter identified in item 7.

Note.—If more than two transporters are used, enter each additional transporter's company name and U.S. EPA twelve digit identification number in items 24-27 on the Continuation Sheet (EPA Form 8700-22A). Each Continuation Sheet has space to record two additional transporters. Every transporter used between the generator and the designated facility must be listed.

Item 9. Designated Facility Name and Site Address

Enter the company name and site address of the facility designated to receive the waste listed on this Manifest. The address must be the site address, which may differ from the company mailing address.

Item 10. U.S. EPA ID Number

Enter the U.S. EPA twelve digit identification number of the designated facility identified in item 9.

Item 11. U.S. DOT Description [Including Proper Shipping Name, Hazard Class, and ID Number (UN/NA)]

Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste as identified in 49 CFR 171 through 177.

Note.—If additional space is needed for waste descriptions, enter these additional descriptions in item 28 on the Continuation Sheet (EPA Form 8700-22A).

Item 12. Containers (No. and Type)

Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.

Table I -- Types of Containers

DM = Metal drums, barrels, kegs	CY = Cylinders
DW = Wooden drums, barrels, kegs	CM = Metal boxes, cartons, cases (including roll-offs)
DF = Fiberboard or plastic drums, barrels, kegs	CW = Wooden boxes, cartons, cases
TP = Tanks portable	CF = Fiber or plastic boxes, cartons, cases
TT = Cargo tanks (tank trucks)	BA = Burlap, cloth, paper or plastic bags
TC = Tank cars	
DT = Dump truck	

Item 13. Total Quantity

Enter the total quantity of waste described on each line.

Item 14. Unit (Wt./Vol.)

Enter the appropriate abbreviation from Table II (below) for the unit of measure.

Table II -- Units of Measure

G = Gallons (liquids only)	L = Liters (liquids only)
P = Pounds	K = Kilograms
T = Tons (2000 lbs)	M = Metric tons (1000 kg)
Y = Cubic yards	N = Cubic meters

Item 15. Special Handling Instructions and Additional Information

Generators may use this space to indicate special transportation, treatment, storage, or disposal information or Bill of Lading information. States may not require additional, new, or different information in this space. For international shipments, generators must

enter in this space the point of departure (City and State) for those shipments destined for treatment, storage, or disposal outside the jurisdiction of the United States.

Item 16. Generator's Certification

The generator must read, sign (by hand), and date the certification statement. If a mode *other than* highway is used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below. If another mode *in addition to* the highway mode is used, enter the appropriate additional mode (e.g., *and rail*) in the space below.

Primary exporters shipping hazardous wastes to a facility located outside of the United States must add to the end of the first sentence of the certification the following words "and conforms to the terms of the EPA Acknowledgment of Consent to the shipment."

In signing the waste minimization certification statement, those generators who have not been exempted by statute or regulation from the duty to make a waste minimization certification under section 3002(b) of RCRA are also certifying that they have complied with the waste minimization requirements.

Generators may preprint the words, "On behalf of" in the signature block or may hand write this statement on the signature block prior to signing the generator certifications.

Note.—All of the above information *except* the handwritten signature required in item 16 may be preprinted.

TRANSPORTERS

Item 17. Transporter 1 Acknowledgement of Receipt of Materials

Enter the name of the person accepting the waste on behalf of the first transporter. That person must acknowledge acceptance of the waste described on the Manifest by signing and entering the date of receipt.

Item 18. Transporter 2 Acknowledgement of Receipt of Materials

Enter, if applicable, the name of the person accepting the waste on behalf of the second transporter. That person must acknowledge acceptance of the waste described on the Manifest by signing and entering the date of receipt.

Note.—International Shipments -- Transporter Responsibilities.

Exports—Transporters must sign and enter the date the waste left the United States in item 15 of Form 8700-22.

Imports—Shipments of hazardous waste regulated by RCRA and transported into the United States from another country must upon entry be accompanied by the U.S. EPA Uniform Hazardous Waste Manifest. Transporters who transport hazardous waste into the United States from another country are responsible for completing the Manifest (40 CFR 263.10(c)(1)).

OWNERS AND OPERATORS OF TREATMENT, STORAGE, OR DISPOSAL FACILITIES

Item 19. Discrepancy Indication Space

The authorized representative of the designated (or alternate) facility's owner or operator must note in this space any significant discrepancy between the waste described on the Manifest and the waste actually received at the facility.

Owners and operators of facilities located in unauthorized States (i.e., the U.S. EPA administers the hazardous waste management program) who cannot resolve significant discrepancies within 15 days of receiving the waste must submit to their Regional Administrator (see list below) a letter with a copy of the Manifest at issue describing the discrepancy and attempts to reconcile it (40 CFR 264.72 and 265.72).

Owners and operators of facilities located in authorized States (i.e., those States that have received authorization from the U.S. EPA to administer the hazardous waste program) should contact their State agency for information on State Discrepancy Report requirements.

EPA Regional Administrators

Regional Administrator, U.S. EPA Region I, J.F. Kennedy Fed. Bldg., Boston, MA 02203

Regional Administrator, U.S. EPA Region II, 26 Federal Plaza, New York, NY 10278

Regional Administrator, U.S. EPA Region III, 6th and Walnut Sts., Philadelphia, PA 19106

Regional Administrator, U.S. EPA Region IV, 345 Courtland St., NE., Atlanta, GA 30365

Regional Administrator, U.S. EPA Region V, 230 S. Dearborn St., Chicago, IL 60604

Regional Administrator, U.S. EPA Region VI, 1201 Elm Street, Dallas, TX 75270

Regional Administrator, U.S. EPA Region VII, 324 East 11th Street, Kansas City, MO 64106

Regional Administrator, U.S. EPA Region VIII, 1860 Lincoln Street, Denver, CO 80295

Regional Administrator, U.S. EPA Region IX, 215 Fremont Street, San Francisco, CA 94105

Regional Administrator, U.S. EPA Region X, 1200 Sixth Avenue, Seattle, WA 98101

Item 20. Facility Owner or Operator: Certification of Receipt of Hazardous Materials Covered by This Manifest Except as Noted in Item 19

Print or type the name of the person accepting the waste on behalf of the owner or operator of the facility. That person must acknowledge acceptance of the waste described on the Manifest by signing and entering the date of receipt.

Items A-K are not required by Federal regulations for intra- or interstate transportation. However, States may require generators and owners or operators of treatment, storage, or disposal facilities to complete some or all of items A-K as part of State manifest reporting requirements. Generators and owners and operators of treatment, storage, or disposal facilities are advised to contact State officials for guidance on completing the shaded areas of the Manifest.

UNIFORM HAZARDOUS
WASTE MANIFEST

1. Generator's US EPA ID No.

Manifest
Document No.

2. Page 1

of 1

Information in the shaded areas is
not required by Federal law.

OHS.FND.S.O.803.8000.14

3. Generator's Name and Mailing Address

US EPA REGION 5
77 W. JACKSON BLVD.
CHICAGO, ILL. 60664JEFFERSON PROCESSING
4243 COUNTY RD. 74
MINGO JCT., OH.

4. Generator's Phone (312) 886-7182

43938

5. Transporter 1 Company Name

Enviroserve

6. US EPA ID Number

D.H.D.9.8.7.0.5.0.5.6.4

7. Transporter 2 Company Name

8. US EPA ID Number

.....

9. Designated Facility Name and Site Address

Environmental Protection Svcs., Inc.
4 Industrial Park Drive
Wheeling, W.V. 26003

10. US EPA ID Number

W.V.D.9.8.8.7.1.0.6.7.3

A. State Manifest Document Number

B. State Generator's ID

C. State Transporter's ID 77160HW

D. Transporter's Phone 800-642-1311

E. State Transporter's ID

F. Transporter's Phone

G. State Facility's ID

H. Facility's Phone

304-232-1590

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)

HM

a. Non DOT Regulated Polychlorinated
X Biphenyls

12. Containers

No.

Type

13. Total
Quantity14. Unit
Wt/Vol

15. Waste No.

001CM35.454K

13. Additional Descriptions for Materials Listed Above

Date taken out of service 8/26/00

K. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information

11a. C-657612 / SS-L / core

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name

Signature

Month Day Year

Thomas Cook

TH Cook

10/25/00

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

Month Day Year

William Bell

William Bell

10/25/00

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

Month Day Year

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name

Signature

Month Day Year

Emergency Contact Telephone Number

Please print or type
(Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039. Expires 9-30-99

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address US EPA REGION 5 77 W. JACKSON BLVD. CHICAGO, ILL. 60664 4. Generator's Phone (312) 886-7182		JEFFERSON PROCESSING 4243 COUNTY RD. 74 MINGO JCT., OH. 43938		A. State Manifest Document Number		
5. Transporter 1 Company Name Environco, Inc.		6. US EPA ID Number OH-D9-8-7-0-5-05-6-4		C. State Transporter's ID 77160HW		
7. Transporter 2 Company Name		8. US EPA ID Number		D. Transporter's Phone 800-642-1311		
9. Designated Facility Name and Site Address Environmental Protection Svcs., Inc. 4 Industrial Park Drive Wheeling, W.V. 26003		10. US EPA ID Number W.V.-D9-8-8-7-7-0-6-7-3		E. State Transporter's ID		
				F. Transporter's Phone		
				G. State Facility's ID		
				H. Facility's Phone 304-232-1590		
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers		13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. <input checked="" type="checkbox"/> HM Non DOT Regulated Polychlorinated X Biphenyls		No.	Type			
b.						
c.						
d.						
J. Additional Descriptions for Materials Listed Above Date taken out of service 8/26/00		K. Handling Codes for Wastes Listed Above				
15. Special Handling Instructions and Additional Information 11a. C-657612 / SS-L / core						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.						
Printed/Typed Name [Signature]		Signature [Signature]		Month Day Year 10 2 2000		
17. Transporter 1 Acknowledgement of Receipt of Materials						
Printed/Typed Name William Bell		Signature William Bell		Month Day Year 10 2 2000		
18. Transporter 2 Acknowledgement of Receipt of Materials						
Printed/Typed Name		Signature		Month Day Year		
19. Discrepancy Indication Space						
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.						
Printed/Typed Name		Signature		Month Day Year		

UNIFORM HAZARDOUS WASTE MANIFEST AND INSTRUCTIONS EPA FORM 8700-22

U.S. EPA Form 8700-22

Read all instructions before completing this form.

This form has been designed for use on a 12-pitch (elite) typewriter; a firm point pen may also be used - press down hard.

Federal regulations require generators and transporters of hazardous waste and owners or operators of hazardous waste treatment, storage, and disposal facilities to use this form (8700-22) and, if necessary, the continuation sheet (Form 8700-22A) for both inter- and intrastate transportation.

Federal regulations also require generators and transporters of hazardous waste and owners or operators of hazardous waste treatment, storage and disposal facilities to complete the following information:

GENERATORS

Item 1. Generator's U.S. EPA ID Number - Manifest Document Number

Enter the generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this Manifest (e.g., 00001) by the generator.

Item 2. Page 1 of -

Enter the total number of pages used to complete this Manifest, i.e., the first page (EPA Form 8700-22) plus the number of Continuation Sheets (EPA Form 8700-22A), if any.

Item 3. Generator's Name and Mailing Address

Enter the name and mailing address of the generator. The address should be the location that will manage the returned Manifest forms.

Item 4. Generator's Phone Number

Enter a telephone number where an authorized agent of the generator may be reached in the event of an emergency.

Item 5. Transporter 1 Company Name

Enter the company name of the first transporter who will transport the waste.

Item 6. U.S. EPA ID Number

Enter the U.S. EPA twelve digit identification number of the first transporter identified in item 5.

Item 7. Transporter 2 Company Name

If applicable, enter the company name of the second transporter who will transport the waste. If more than two transporters are used to transport the waste, use a Continuation Sheet(s) (EPA Form 8700-22A) and list the transporters in the order they will be transporting the waste.

Item 8. U.S. EPA ID Number

If applicable, enter the U.S. EPA twelve digit identification number of the second transporter identified in item 7.

Note.-If more than two transporters are used, enter each additional transporter's company name and U.S. EPA twelve digit identification number in items 24-27 on the Continuation Sheet (EPA Form 8700-22A). Each Continuation Sheet has space to record two additional transporters. Every transporter used between the generator and the designated facility must be listed.

Item 9. Designated Facility Name and Site Address

Enter the company name and site address of the facility designated to receive the waste listed on this Manifest. The address must be the site address, which may differ from the company mailing address.

Item 10. U.S. EPA ID Number

Enter the U.S. EPA twelve digit identification number of the designated facility identified in item 9.

Item 11. U.S. DOT Description [Including Proper Shipping Name, Hazard Class, and ID Number (UN/NA)]

Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste as identified in 49 CFR 171 through 177.

Note.-If additional space is needed for waste descriptions, enter these additional descriptions in item 28 on the Continuation Sheet (EPA Form 8700-22A).

Item 12. Containers (No. and Type)

Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.

Table I - Types of Containers

DM = Metal drums, barrels, kegs	CY = Cylinders
DW = Wooden drums, barrels, kegs	CM = Metal boxes, cartons, cases (including roll-offs)
DF = Fiberboard or plastic drums, barrels, kegs	CW = Wooden boxes, cartons, cases
TP = Tanks portable	CF = Fiber or plastic boxes, cartons, cases
TT = Cargo tanks (tank trucks)	BA = Burlap, cloth, paper or plastic bags
TC = Tank cars	
DT = Dump truck	

Item 13. Total Quantity

Enter the total quantity of waste described on each line.

Item 14. Unit (Wt./Vol.)

Enter the appropriate abbreviation from Table II (below) for the unit of measure.

Table II - Units of Measure

G = Gallons (liquids only)	L = Liters (liquids only)
P = Pounds	K = Kilograms
T = Tons (2000 lbs)	M = Metric tons (1000 kg)
Y = Cubic yards	N = Cubic meters

Item 15. Special Handling Instructions and Additional Information

Generators may use this space to indicate special transportation, treatment, storage, or disposal information or Bill of Lading information. States may not require additional, new, or different information in this space. For international shipments, generators must

enter in this space the point of departure (City and State) for those shipments destined for treatment, storage, or disposal outside the jurisdiction of the United States.

Item 16. Generator's Certification

The generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below. If another mode in addition to the highway mode is used, enter the appropriate additional mode (e.g., and rail) in the space below.

Primary exporters shipping hazardous wastes to a facility located outside of the United States must add to the end of the first sentence of the certification the following words "and conforms to the terms of the EPA Acknowledgment of Consent to the shipment."

In signing the waste minimization certification statement, those generators who have not been exempted by statute or regulation from the duty to make a waste minimization certification under section 3002(b) of RCRA are also certifying that they have complied with the waste minimization requirements.

Generators may preprint the words, "On behalf of" in the signature block or may hand write this statement on the signature block prior to signing the generator certifications.

Note.-All of the above information except the handwritten signature required in item 16 may be preprinted.

TRANSPORTERS

Item 17. Transporter 1 Acknowledgement of Receipt of Materials

Enter the name of the person accepting the waste on behalf of the first transporter. That person must acknowledge acceptance of the waste described on the Manifest by signing and entering the date of receipt.

Item 18. Transporter 2 Acknowledgement of Receipt of Materials

Enter, if applicable, the name of the person accepting the waste on behalf of the second transporter. That person must acknowledge acceptance of the waste described on the Manifest by signing and entering the date of receipt.

Note.-International Shipments - Transporter Responsibilities.

Exports-Transporters must sign and enter the date the waste left the United States in item 15 of Form 8700-22.

Imports-Shipments of hazardous waste regulated by RCRA and transported into the United States from another country must upon entry be accompanied by the U.S. EPA Uniform Hazardous Waste Manifest. Transporters who transport hazardous waste into the United States from another country are responsible for completing the Manifest (40 CFR 263.10(c)(1)).

OWNERS AND OPERATORS OF TREATMENT, STORAGE, OR DISPOSAL FACILITIES

Item 19. Discrepancy Indication Space

The authorized representative of the designated (or alternate) facility's owner or operator must note in this space any significant discrepancy between the waste described on the Manifest and the waste actually received at the facility.

Owners and operators of facilities located in unauthorized States (i.e., the U.S. EPA administers the hazardous waste management program) who cannot resolve significant discrepancies within 15 days of receiving the waste must submit to their Regional Administrator (see list below) a letter with a copy of the Manifest at issue describing the discrepancy and attempts to reconcile it (40 CFR 264.72 and 265.72).

Owners and operators of facilities located in authorized States (i.e., those States that have received authorization from the U.S. EPA to administer the hazardous waste program) should contact their State agency for information on State Discrepancy Report requirements.

EPA Regional Administrators

Regional Administrator, U.S. EPA Region I, J.F. Kennedy Fed. Bldg., Boston, MA 02203

Regional Administrator, U.S. EPA Region II, 26 Federal Plaza, New York, NY 10278

Regional Administrator, U.S. EPA Region III, 6th and Walnut Sts., Philadelphia, PA 19106

Regional Administrator, U.S. EPA Region IV, 345 Courtland St., NE., Atlanta, GA 30365

Regional Administrator, U.S. EPA Region V, 230 S. Dearborn St., Chicago, IL 60604

Regional Administrator, U.S. EPA Region VI, 1201 Elm Street, Dallas, TX 75270

Regional Administrator, U.S. EPA Region VII, 324 East 11th Street, Kansas City, MO 64106

Regional Administrator, U.S. EPA Region VIII, 1860 Lincoln Street, Denver, CO 80295

Regional Administrator, U.S. EPA Region IX, 215 Fremont Street, San Francisco, CA 94105

Regional Administrator, U.S. EPA Region X, 1200 Sixth Avenue, Seattle, WA 98101

Item 20. Facility Owner or Operator: Certification of Receipt of Hazardous Materials Covered by This Manifest Except as Noted in Item 19

Print or type the name of the person accepting the waste on behalf of the owner or operator of the facility. That person must acknowledge acceptance of the waste described on the Manifest by signing and entering the date of receipt.

Items A-K are not required by Federal regulations for intra- or interstate transportation. However, States may require generators and owners or operators of treatment, storage, or disposal facilities to complete some or all of items A-K as part of State manifest reporting requirements. Generators and owners and operators of treatment, storage, or disposal facilities are advised to contact State officials for guidance on completing the shaded areas of the Manifest.

Emergency Contact Telephone Number

UNIFORM HAZARDOUS
WASTE MANIFEST

1. Generator's US EPA ID No.

Manifest
Document No.2. Page 1
of 1Information in the shaded areas is
not required by Federal law.

6 H S F N D 5 0 8 0 3 8 0 0 0 1 2

3. Generator's Name and Mailing Address

USEPA REGION 5
77 W. JACKSON BLVD.
CHICAGO, ILL. 60604
4. Generator's Phone (312) 886-7182JEFFERSON PROCESSING
4243 COUNTY RD. 74
MINGO JCT., OH.
43938

A. State Manifest Document Number

B. State Generator's ID

5. Transporter 1 Company Name

Enviroserve

6. US EPA ID Number

OH-D-9-8-7-0-5-0-5-6-4

C. State Transporter's ID 77160HW

D. Transporter's Phone 800-642-1311

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address

Environmental Protection Svcs., Inc.
4 Industrial Park Drive
Wheeling, W.V. 26003

10. US EPA ID Number

W.V.-D-9-8-7-7-0-6-7-3

G. State Facility's ID

H. Facility's Phone

304-232-1590

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)

HM

12. Containers

No.

Type

13. Total
Quantity14. Unit
Wt/Vol

1. Waste No.

a. ☒ Non DOT Regulated Polychlorinated
Biphenyls

0.01 CM 1.0; 7.7.2 K

b. ☒ Non DOT Regulated Polychlorinated
Biphenyls

0.01 CM 1.0; 7.7.2 K

c.

d.

J. Additional Descriptions for Materials Listed Above

Date taken out of service, 8/26/00

K. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information

11a. C-657626 / J1-H

11b. C-657630 / J1-E

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name

Thomas Cook

Signature

[Signature]

Month Day Year

11-02-510-0

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

William Bell

Signature

[Signature]

Month Day Year

11-02-510-0

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

Month Day Year

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name

Signature

Month Day Year

ORIGINAL - RETURN TO GENERATOR

Emergency Contact Telephone Number

Please print or type
(Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039. Expires 9-30-99

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address USEPA REGION 5 77 W. JACKSON BLVD. CHICAGO ILL. 60604 4. Generator's Phone () 312 886-7182		JEFFERSON PROCESSING 4243 COUNTY RD. 74 MINGO JCT., OH. 43938		A. State Manifest Document Number		
5. Transporter 1 Company Name Enviroserve		6. US EPA ID Number 04-D-9-8-7-0-5-0-5-6-4		C. State Transporter's ID 77160HW		
7. Transporter 2 Company Name		8. US EPA ID Number		D. Transporter's Phone 800-647-1311		
9. Designated Facility Name and Site Address Environmental Protection Svs., Inc. 4 Industrial Park Drive Wheeling, W.V. 26003		10. US EPA ID Number WV-D-9-8-8-7-7-0-6-7-3		E. State Transporter's ID		
				F. Transporter's Phone		
				G. State Facility's ID		
				H. Facility's Phone 304-232-1590		
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.	
a. <input checked="" type="checkbox"/> Non DOT Regulated Polychlorinated Biphenyls		No. Type				
b. <input checked="" type="checkbox"/> Non DOT Regulated Polychlorinated Biphenyls			0.01 CM 10,77.2 K			
c.			0.01 CM 10,77.2 K			
d.						
J. Additional Descriptions for Materials Listed Above Date taken out of service. 8/26/00		K. Handling Codes for Wastes Listed Above				
15. Special Handling Instructions and Additional Information 11a. C-657626 / J1-H 11b. C-657630 / J1-E						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.						
Printed/Typed Name H. L. Bell		Signature H. L. Bell		Month Day Year 11 02 50 00		
17. Transporter 1 Acknowledgement of Receipt of Materials						
Printed/Typed Name William Bell		Signature William Bell		Month Day Year 11 02 50 00		
18. Transporter 2 Acknowledgement of Receipt of Materials						
Printed/Typed Name		Signature		Month Day Year		
19. Discrepancy Indication Space						
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.						
Printed/Typed Name		Signature		Month Day Year		

UNIFORM HAZARDOUS WASTE MANIFEST AND INSTRUCTIONS EPA FORM 8700-22

U.S. EPA Form 8700-22

Read all instructions before completing this form.

This form has been designed for use on a 12-pitch (elite) typewriter; a firm point pen may also be used - press down hard.

Federal regulations require generators and transporters of hazardous waste and owners or operators of hazardous waste treatment, storage, and disposal facilities to use this form (8700-22) and, if necessary, the continuation sheet (Form 8700-22A) for both inter- and intrastate transportation.

Federal regulations also require generators and transporters of hazardous waste and owners or operators of hazardous waste treatment, storage and disposal facilities to complete the following information:

GENERATORS

Item 1. Generator's U.S. EPA ID Number - Manifest Document Number

Enter the generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this Manifest (e.g., 00001) by the generator.

Item 2. Page 1 of -

Enter the total number of pages used to complete this Manifest, i.e., the first page (EPA Form 8700-22) plus the number of Continuation Sheets (EPA Form 8700-22A), if any.

Item 3. Generator's Name and Mailing Address

Enter the name and mailing address of the generator. The address should be the location that will manage the returned Manifest forms.

Item 4. Generator's Phone Number

Enter a telephone number where an authorized agent of the generator may be reached in the event of an emergency.

Item 5. Transporter 1 Company Name

Enter the company name of the first transporter who will transport the waste.

Item 6. U.S. EPA ID Number

Enter the U.S. EPA twelve digit identification number of the first transporter identified in item 5.

Item 7. Transporter 2 Company Name

If applicable, enter the company name of the second transporter who will transport the waste. If more than two transporters are used to transport the waste, use a Continuation Sheet(s) (EPA Form 8700-22A) and list the transporters in the order they will be transporting the waste.

Item 8. U.S. EPA ID Number

If applicable, enter the U.S. EPA twelve digit identification number of the second transporter identified in item 7.

Note.-If more than two transporters are used, enter each additional transporter's company name and U.S. EPA twelve digit identification number in items 24-27 on the Continuation Sheet (EPA Form 8700-22A). Each Continuation Sheet has space to record two additional transporters. Every transporter used between the generator and the designated facility must be listed.

Item 9. Designated Facility Name and Site Address

Enter the company name and site address of the facility designated to receive the waste listed on this Manifest. The address must be the site address, which may differ from the company mailing address.

Item 10. U.S. EPA ID Number

Enter the U.S. EPA twelve digit identification number of the designated facility identified in item 9.

Item 11. U.S. DOT Description [including Proper Shipping Name, Hazard Class, and ID Number (UN/NA)]

Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste as identified in 49 CFR 171 through 177.

Note.-If additional space is needed for waste descriptions, enter these additional descriptions in item 28 on the Continuation Sheet (EPA Form 8700-22A).

Item 12. Containers (No. and Type)

Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.

Table I - Types of Containers

DM = Metal drums, barrels, kegs	CY = Cylinders
DW = Wooden drums, barrels, kegs	CM = Metal boxes, cartons, cases (including roll-offs)
DF = Fiberboard or plastic drums, barrels, kegs	CW = Wooden boxes, cartons, cases
TP = Tanks portable	CF = Fiber or plastic boxes, cartons, cases
TT = Cargo tanks (tank trucks)	BA = Burlap, cloth, paper or plastic bags
TC = Tank cars	
DT = Dump truck	

Item 13. Total Quantity

Enter the total quantity of waste described on each line.

Item 14. Unit (Wt./Vol.)

Enter the appropriate abbreviation from Table II (below) for the unit of measure.

Table II - Units of Measure

G = Gallons (liquids only)	L = Liters (liquids only)
P = Pounds	K = Kilograms
T = Tons (2000 lbs)	M = Metric tons (1000 kg)
Y = Cubic yards	N = Cubic meters

Item 15. Special Handling Instructions and Additional Information

Generators may use this space to indicate special transportation, treatment, storage, or disposal information or Bill of Lading information. States may not require additional, new, or different information in this space. For international shipments, generators must

enter in this space the point of departure (City and State) for those shipments destined for treatment, storage, or disposal outside the jurisdiction of the United States.

Item 16. Generator's Certification

The generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below. If another mode in addition to the highway mode is used, enter the appropriate additional mode (e.g., and rail) in the space below.

Primary exporters shipping hazardous wastes to a facility located outside of the United States must add to the end of the first sentence of the certification the following words "and conforms to the terms of the EPA Acknowledgment of Consent to the shipment."

In signing the waste minimization certification statement, those generators who have not been exempted by statute or regulation from the duty to make a waste minimization certification under section 3002(b) of RCRA are also certifying that they have complied with the waste minimization requirements.

Generators may preprint the words "On behalf of" in the signature block or may hand write this statement on the signature block prior to signing the generator certifications.

Note.-All of the above information except the handwritten signature required in item 16 may be preprinted.

TRANSPORTERS

Item 17. Transporter 1 Acknowledgement of Receipt of Materials

Enter the name of the person accepting the waste on behalf of the first transporter. That person must acknowledge acceptance of the waste described on the Manifest by signing and entering the date of receipt.

Item 18. Transporter 2 Acknowledgement of Receipt of Materials

Enter, if applicable, the name of the person accepting the waste on behalf of the second transporter. That person must acknowledge acceptance of the waste described on the Manifest by signing and entering the date of receipt.

Note.-International Shipments - Transporter Responsibilities.

Exports-Transporters must sign and enter the date the waste left the United States in item 15 of Form 8700-22.

Imports-Shipments of hazardous waste regulated by RCRA and transported into the United States from another country must upon entry be accompanied by the U.S. EPA Uniform Hazardous Waste Manifest. Transporters who transport hazardous waste into the United States from another country are responsible for completing the Manifest (40 CFR 263.10(c)(1)).

OWNERS AND OPERATORS OF TREATMENT, STORAGE, OR DISPOSAL FACILITIES

Item 19. Discrepancy Indication Space

The authorized representative of the designated (or alternate) facility's owner or operator must note in this space any significant discrepancy between the waste described on the Manifest and the waste actually received at the facility.

Owners and operators of facilities located in unauthorized States (i.e., the U.S. EPA administers the hazardous waste management program) who cannot resolve significant discrepancies within 15 days of receiving the waste must submit to their Regional Administrator (see list below) a letter with a copy of the Manifest at issue describing the discrepancy and attempts to reconcile it (40 CFR 264.72 and 265.72).

Owners and operators of facilities located in authorized States (i.e., those States that have received authorization from the U.S. EPA to administer the hazardous waste program) should contact their State agency for information on State Discrepancy Report requirements.

EPA Regional Administrators

Regional Administrator, U.S. EPA Region I, J.F. Kennedy Fed. Bldg., Boston, MA 02203

Regional Administrator, U.S. EPA Region II, 26 Federal Plaza, New York, NY 10278

Regional Administrator, U.S. EPA Region III, 6th and Walnut Sts., Philadelphia, PA 19106

Regional Administrator, U.S. EPA Region IV, 345 Courtland St., NE., Atlanta, GA 30365

Regional Administrator, U.S. EPA Region V, 230 S. Dearborn St., Chicago, IL 60604

Regional Administrator, U.S. EPA Region VI, 1201 Elm Street, Dallas, TX 75270

Regional Administrator, U.S. EPA Region VII, 324 East 11th Street, Kansas City, MO 64106

Regional Administrator, U.S. EPA Region VIII, 1860 Lincoln Street, Denver, CO 80295

Regional Administrator, U.S. EPA Region IX, 215 Freemont Street, San Francisco, CA 94105

Regional Administrator, U.S. EPA Region X, 1200 Sixth Avenue, Seattle, WA 98101

Item 20. Facility Owner or Operator: Certification of Receipt of Hazardous Materials Covered by This Manifest Except as Noted in Item 19

Print or type the name of the person accepting the waste on behalf of the owner or operator of the facility. That person must acknowledge acceptance of the waste described on the Manifest by signing and entering the date of receipt.

Items A-K are not required by Federal regulations for intra- or interstate transportation. However, States may require generators and owners or operators of treatment, storage, or disposal facilities to complete some or all of items A-K as part of State manifest reporting requirements. Generators and owners and operators of treatment, storage, or disposal facilities are advised to contact State officials for guidance on completing the shaded areas of the Manifest.

Emergency Contact Telephone Number

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.

045.FND.50.803.80001.1

Manifest Document No.

2. Page 1 of 1

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address

USEPA REGION 5
77 W. JACKSON BLVD.
CHICAGO, ILL.

JEFFERSON PROCESSING
4243 COUNTY RD. 74
MINGO JCT., OH.

4. Generator's Phone (312) 886-7182

43938

5. Transporter 1 Company Name

Enviroserve

6. US EPA ID Number

10.HD9.8.7.05.05.6.4

7. Transporter 2 Company Name

8. US EPA ID Number

.....

9. Designated Facility Name and Site Address

Environmental Protection Svcs, Inc.
4 Industrial Park Drive
Wheeling, W.V. 26003

10. US EPA ID Number

10.V.D.98.8.7.7.0.6.7.3

A. State Manifest Document Number

B. State Generator's ID

C. State Transporter's ID 77160HW

D. Transporter's Phone 800-642-1311

E. State Transporter's ID

F. Transporter's Phone

G. State Facility's ID

H. Facility's Phone

304-232-1590

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)

HM

a. Non Dot Regulated Polychlorinated
X Biphenyls

0.01 CM 10.7.7.2 K

b. Non Dot Regulated Polychlorinated
X Biphenyls

0.01 CM 10.7.7.2 K

c.

d.

12. Containers

No.

Type

13. Total Quantity

14. Unit Wt/Vol

15. Waste No.

J. Additional Descriptions for Materials Listed Above

Date taken out of service. 8/26/00

K. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information

11a. C-656576/J2-P

11b. C-657628/J1-D

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name

Thomas Cook

Signature

TL Cook

Month Day Year

11.02.410.0

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

MICHAEL E. ERNEST

Signature

Michael E. Ernest

Month Day Year

11.02.410.0

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

Month Day Year

.....

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name

Signature

Month Day Year

.....

ORIGINAL - RETURN TO GENERATOR

Emergency Contact Telephone Number

Please print or type
(Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039. Expires 9-30-99

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address USEPA REGION 5 77 W. JACKSON BLVD. CHICAGO, ILL.		JEFFERSON PROCESSING 4243 COUNTY RD. 74 MINGO JCT., OH.		A. State Manifest Document Number		
4. Generator's Phone (312) 886-7182		43938		B. State Generator's ID		
5. Transporter 1 Company Name Envireserve		6. US EPA ID Number OH.D9.8.7.0.5.0.5.6.4		C. State Transporter's ID 77160HW		
7. Transporter 2 Company Name		8. US EPA ID Number		D. Transporter's Phone 800-642-1311		
9. Designated Facility Name and Site Address Environmental Protection Svcs., Inc. 4 Industrial Park Drive Wheeling, W.V. 26003		10. US EPA ID Number W.V.D.9.8.8.7.7.0.6.7.3		E. State Transporter's ID		
				F. Transporter's Phone		
				G. State Facility's ID		
				H. Facility's Phone 304-232-1590		
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers		13. Total Quantity	14. Unit Wt/Vol	15. Waste No.
a. <input checked="" type="checkbox"/> HM Non Dot Regulated Polychlorinated Biphenyls		No. Type				
b. <input checked="" type="checkbox"/> Non Dot Regulated Polychlorinated Biphenyls		0.0.1 C.M. 1.0.7.7.2 K				
c.	
d.	
J. Additional Descriptions for Materials Listed Above		K. Handling Codes for Wastes Listed Above				
Date taken out of service. 8/26/00						
15. Special Handling Instructions and Additional Information						
11a. C-656576/32-P						
11b. C-657628/31-D						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.						
Printed/Typed Name Thomas Cook		Signature TH Cook		Month Day Year 11/02/00		
17. Transporter 1 Acknowledgement of Receipt of Materials						
Printed/Typed Name MICHAEL E. ERNEST		Signature Michael E. Ernest		Month Day Year 11/02/00		
18. Transporter 2 Acknowledgement of Receipt of Materials						
Printed/Typed Name		Signature		Month Day Year		
19. Discrepancy Indication Space						
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.						
Printed/Typed Name		Signature		Month Day Year		

UNIFORM HAZARDOUS WASTE MANIFEST AND INSTRUCTIONS EPA FORM 8700-22

U.S. EPA Form 8700-22

Read all instructions before completing this form.

This form has been designed for use on a 12-pitch (elite) typewriter; a firm point pen may also be used — press down hard.

Federal regulations require generators and transporters of hazardous waste and owners or operators of hazardous waste treatment, storage, and disposal facilities to use this form (8700-22) and, if necessary, the continuation sheet (Form 8700-22A) for both inter- and intrastate transportation.

Federal regulations also require generators and transporters of hazardous waste and owners or operators of hazardous waste treatment, storage and disposal facilities to complete the following information:

GENERATORS

Item 1. Generator's U.S. EPA ID Number — Manifest Document Number

Enter the generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this Manifest (e.g., 00001) by the generator.

Item 2. Page 1 of —

Enter the total number of pages used to complete this Manifest, i.e., the first page (EPA Form 8700-22) plus the number of Continuation Sheets (EPA Form 8700-22A), if any.

Item 3. Generator's Name and Mailing Address

Enter the name and mailing address of the generator. The address should be the location that will manage the returned Manifest forms.

Item 4. Generator's Phone Number

Enter a telephone number where an authorized agent of the generator may be reached in the event of an emergency.

Item 5. Transporter 1 Company Name

Enter the company name of the first transporter who will transport the waste.

Item 6. U.S. EPA ID Number

Enter the U.S. EPA twelve digit identification number of the first transporter identified in item 5.

Item 7. Transporter 2 Company Name

If applicable, enter the company name of the second transporter who will transport the waste. If more than two transporters are used to transport the waste, use a Continuation Sheet(s) (EPA Form 8700-22A) and list the transporters in the order they will be transporting the waste.

Item 8. U.S. EPA ID Number

If applicable, enter the U.S. EPA twelve digit identification number of the second transporter identified in item 7.

Note.—If more than two transporters are used, enter each additional transporter's company name and U.S. EPA twelve digit identification number in items 24-27 on the Continuation Sheet (EPA Form 8700-22A). Each Continuation Sheet has space to record two additional transporters. Every transporter used between the generator and the designated facility must be listed.

Item 9. Designated Facility Name and Site Address

Enter the company name and site address of the facility designated to receive the waste listed on this Manifest. The address must be the site address, which may differ from the company mailing address.

Item 10. U.S. EPA ID Number

Enter the U.S. EPA twelve digit identification number of the designated facility identified in item 9.

Item 11. U.S. DOT Description [Including Proper Shipping Name, Hazard Class, and ID Number (UN/NA)]

Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste as identified in 49 CFR 171 through 177.

Note.—If additional space is needed for waste descriptions, enter these additional descriptions in item 28 on the Continuation Sheet (EPA Form 8700-22A).

Item 12. Containers (No. and Type)

Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.

Table I — Types of Containers

DM = Metal drums, barrels, kegs	CY = Cylinders
DW = Wooden drums, barrels, kegs	CM = Metal boxes, cartons, cases (including roll-offs)
DF = Fiberboard or plastic drums, barrels, kegs	CW = Wooden boxes, cartons, cases
TP = Tanks portable	CF = Fiber or plastic boxes, cartons, cases
TT = Cargo tanks (tank trucks)	BA = Burlap, cloth, paper or plastic bags
TC = Tank cars	
DT = Dump truck	

Item 13. Total Quantity

Enter the total quantity of waste described on each line.

Item 14. Unit (Wt./Vol.)

Enter the appropriate abbreviation from Table II (below) for the unit of measure.

Table II — Units of Measure

G = Gallons (liquids only)	L = Liters (liquids only)
P = Pounds	K = Kilograms
T = Tons (2000 lbs)	M = Metric tons (1000 kg)
Y = Cubic yards	N = Cubic meters

Item 15. Special Handling Instructions and Additional Information

Generators may use this space to indicate special transportation, treatment, storage, or disposal information or Bill of Lading information. States may not require additional, new, or different information in this space. For international shipments, generators must

enter in this space the point of departure (City and State) for those shipments destined for treatment, storage, or disposal outside the jurisdiction of the United States.

Item 16. Generator's Certification

The generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below. If another mode in addition to the highway mode is used, enter the appropriate additional mode (e.g., and rail) in the space below.

Primary exporters shipping hazardous wastes to a facility located outside of the United States must add to the end of the first sentence of the certification the following words "and conforms to the terms of the EPA Acknowledgment of Consent to the shipment."

In signing the waste minimization certification statement, those generators who have not been exempted by statute or regulation from the duty to make a waste minimization certification under section 3002(b) of RCRA are also certifying that they have complied with the waste minimization requirements.

Generators may preprint the words "On behalf of" in the signature block or may hand write this statement on the signature block prior to signing the generator certifications.

Note.—All of the above information except the handwritten signature required in item 16 may be preprinted.

TRANSPORTERS

Item 17. Transporter 1 Acknowledgement of Receipt of Materials

Enter the name of the person accepting the waste on behalf of the first transporter. That person must acknowledge acceptance of the waste described on the Manifest by signing and entering the date of receipt.

Item 18. Transporter 2 Acknowledgement of Receipt of Materials

Enter, if applicable, the name of the person accepting the waste on behalf of the second transporter. That person must acknowledge acceptance of the waste described on the Manifest by signing and entering the date of receipt.

Note.—International Shipments — Transporter Responsibilities.

Exports—Transporters must sign and enter the date the waste left the United States in item 15 of Form 8700-22.

Imports—Shipments of hazardous waste regulated by RCRA and transported into the United States from another country must upon entry be accompanied by the U.S. EPA Uniform Hazardous Waste Manifest. Transporters who transport hazardous waste into the United States from another country are responsible for completing the Manifest (40 CFR 263.10(c)(1)).

OWNERS AND OPERATORS OF TREATMENT, STORAGE, OR DISPOSAL FACILITIES

Item 19. Discrepancy Indication Space

The authorized representative of the designated (or alternate) facility's owner or operator must note in this space any significant discrepancy between the waste described on the Manifest and the waste actually received at the facility.

Owners and operators of facilities located in unauthorized States (i.e., the U.S. EPA administers the hazardous waste management program) who cannot resolve significant discrepancies within 15 days of receiving the waste must submit to their Regional Administrator (see list below) a letter with a copy of the Manifest at issue describing the discrepancy and attempts to reconcile it (40 CFR 264.72 and 265.72).

Owners and operators of facilities located in authorized States (i.e., those States that have received authorization from the U.S. EPA to administer the hazardous waste program) should contact their State agency for information on State Discrepancy Report requirements.

EPA Regional Administrators

Regional Administrator, U.S. EPA Region I, J.F. Kennedy Fed. Bldg., Boston, MA 02203

Regional Administrator, U.S. EPA Region II, 26 Federal Plaza, New York, NY 10278

Regional Administrator, U.S. EPA Region III, 6th and Walnut Sts., Philadelphia, PA 19106

Regional Administrator, U.S. EPA Region IV, 345 Courtland St., NE., Atlanta, GA 30365

Regional Administrator, U.S. EPA Region V, 230 S. Dearborn St., Chicago, IL 60604

Regional Administrator, U.S. EPA Region VI, 1201 Elm Street, Dallas, TX 75270

Regional Administrator, U.S. EPA Region VII, 324 East 11th Street, Kansas City, MO 64106

Regional Administrator, U.S. EPA Region VIII, 1860 Lincoln Street, Denver, CO 80295

Regional Administrator, U.S. EPA Region IX, 215 Fremont Street, San Francisco, CA 94105

Regional Administrator, U.S. EPA Region X, 1200 Sixth Avenue, Seattle, WA 98101

Item 20. Facility Owner or Operator: Certification of Receipt of Hazardous Materials Covered by This Manifest Except as Noted in Item 19

Print or type the name of the person accepting the waste on behalf of the owner or operator of the facility. That person must acknowledge acceptance of the waste described on the Manifest by signing and entering the date of receipt.

Items A-K are not required by Federal regulations for intra- or interstate transportation. However, States may require generators and owners or operators of treatment, storage, or disposal facilities to complete some or all of items A-K as part of State manifest reporting requirements. Generators and owners and operators of treatment, storage, or disposal facilities are advised to contact State officials for guidance on completing the shaded areas of the Manifest.

UNIFORM HAZARDOUS
WASTE MANIFEST

1. Generator's US EPA ID No.

Manifest
Document No.2. Page 1
of 1Information in the shaded areas is
not required by Federal law.

3. Generator's Name and Mailing Address

USEPA REGION 5
77 W. JACKSON BLVD.
CHICAGO, ILL. 60604

4. Generator's Phone (312) 886-7182

JEFFERSON PROCESSING
4243 COUNTY RD. 74
MINGO JCT, OH.

43938

5. Transporter 1 Company Name

Enviroserve

6. US EPA ID Number

OH.D.9.8.7.05.05.64

7. Transporter 2 Company Name

8. US EPA ID Number

9. Designated Facility Name and Site Address

Environmental Protection Svcs, Inc
4 Industrial Park Drive
Wheeling, W.V. 26003

10. US EPA ID Number

W.V.D.9.8.8.7.7.0.6.7.3

A. State Manifest Document Number

B. State Generator's ID

C. State Transporter's ID 77160HW

D. Transporter's Phone 800 642-1311

E. State Transporter's ID

F. Transporter's Phone

G. State Facility's ID

H. Facility's Phone

304 232-1590

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)

HM

12. Containers

No.

Type

13.
Total
Quantity14.
Unit
Wt/Vol1.
Waste No.a. X RQ, Polychlorinated Biphenyls, Mixture
Class 9, PG III UN 2315

0.01 CM 4.7.2.7 K

b. X RQ, Polychlorinated Biphenyls, Mixture
Class 9, PG III UN 2315

0.01 CM 4.7.2.7 K

c. X RQ, Polychlorinated Biphenyls, Mixture
Class 9, PG III UN 2315

0.01 CM 4.7.2.7 K

d. X RQ, Polychlorinated Biphenyls, Mixture
Class 9, PG III UN 2315

0.01 CM 4.7.2.7 K

12. Additional Descriptions for Materials Listed Above

Date taken out of service 8/26/00

K. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information

15a. C-503735/J1-I
15b. C-856282/PH-M
15c. C-503737/J2-N

11d. C-856281/J2-Q

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified,
packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.

- ☐ If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name

Thomas Cook

Signature

TH Cook

Month Day Year

11/02/00

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

MICHAEL E. ERNEST

Signature

Michael E. Ernest

Month Day Year

11/02/00

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

Month Day Year

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name

Signature

Month Day Year

Emergency Contact Telephone Number

Please print or type
(Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039. Expires 9-30-99

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address USEPA REGION 5 77 W. JACKSON BLVD. CHICAGO, ILL. 60604		JEFFERSON PROCESSING 4243 COUNTY RD. 74 MINGO JCT, OH. 43938		A. State Manifest Document Number		
4. Generator's Phone (312) 886-7182				B. State Generator's ID		
5. Transporter 1 Company Name Enviroserve		6. US EPA ID Number 0.H.D.9.8.7.0.5.0.5.64		C. State Transporter's ID 77160HW		
7. Transporter 2 Company Name		8. US EPA ID Number		D. Transporter's Phone 800642-1311		
9. Designated Facility Name and Site Address Environmental Protection Svcs., Inc. 4 Industrial Park Drive Wheeling, W.V. 26003		10. US EPA ID Number W.V.D.9.8.8.7.7.0.6.7.3		E. State Transporter's ID		
				F. Transporter's Phone		
				G. State Facility's ID		
				H. Facility's Phone 304 232-1590		
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)				12. Containers	13. Total Quantity	14. Unit Wt/Vol
				No.	Type	1. Waste No.
a.	RM, Polychlorinated Biphenyls, Mixture X Class 9, PG III UN 2315			0.01 CM	4.7.2.7	K
b.	RM, Polychlorinated Biphenyls, Mixture X Class 9, PG III UN 2315			0.01 CM	4.7.2.7	K
c.	RM, Polychlorinated Biphenyls, Mixture X Class 9, PG III UN 2315			0.01 CM	4.7.2.7	K
d.	RM, Polychlorinated Biphenyls, Mixture X Class 9, PG III UN 2315			0.01 CM	4.7.2.7	K
J. Additional Descriptions for Materials Listed Above Date taken out of service 8/26/00				K. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information 11a. C-503735/51-I 11b. C-856282/PH-M 11c. C-503737/52-N 11d. C-856281/52-Q						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.						
Printed/Typed Name Thomas Cook				Signature [Signature]		Month Day Year 11.02.40.00
17. Transporter 1 Acknowledgement of Receipt of Materials						
Printed/Typed Name MICHAEL E. ERNEST				Signature Michael E. Ernest		Month Day Year 11.02.40.00
18. Transporter 2 Acknowledgement of Receipt of Materials						
Printed/Typed Name				Signature		Month Day Year . . .
19. Discrepancy Indication Space						
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.						
Printed/Typed Name				Signature		Month Day Year . . .

UNIFORM HAZARDOUS WASTE MANIFEST AND INSTRUCTIONS EPA FORM 8700-22

U.S. EPA Form 8700-22

Read all instructions before completing this form.

This form has been designed for use on a 12-pitch (elite) typewriter; a firm point pen may also be used - press down hard.

Federal regulations require generators and transporters of hazardous waste and owners or operators of hazardous waste treatment, storage, and disposal facilities to use this form (8700-22) and, if necessary, the continuation sheet (Form 8700-22A) for both inter- and intrastate transportation.

Federal regulations also require generators and transporters of hazardous waste and owners or operators of hazardous waste treatment, storage and disposal facilities to complete the following information:

GENERATORS

Item 1. Generator's U.S. EPA ID Number - Manifest Document Number

Enter the generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this Manifest (e.g., 00001) by the generator.

Item 2. Page 1 of -

Enter the total number of pages used to complete this Manifest, i.e., the first page (EPA Form 8700-22) plus the number of Continuation Sheets (EPA Form 8700-22A), if any.

Item 3. Generator's Name and Mailing Address

Enter the name and mailing address of the generator. The address should be the location that will manage the returned Manifest forms.

Item 4. Generator's Phone Number

Enter a telephone number where an authorized agent of the generator may be reached in the event of an emergency.

Item 5. Transporter 1 Company Name

Enter the company name of the first transporter who will transport the waste.

Item 6. U.S. EPA ID Number

Enter the U.S. EPA twelve digit identification number of the first transporter identified in item 5.

Item 7. Transporter 2 Company Name

If applicable, enter the company name of the second transporter who will transport the waste. If more than two transporters are used to transport the waste, use a Continuation Sheet(s) (EPA Form 8700-22A) and list the transporters in the order they will be transporting the waste.

Item 8. U.S. EPA ID Number

If applicable, enter the U.S. EPA twelve digit identification number of the second transporter identified in item 7.

Note.-If more than two transporters are used, enter each additional transporter's company name and U.S. EPA twelve digit identification number in items 24-27 on the Continuation Sheet (EPA Form 8700-22A). Each Continuation Sheet has space to record two additional transporters. Every transporter used between the generator and the designated facility must be listed.

Item 9. Designated Facility Name and Site Address

Enter the company name and site address of the facility designated to receive the waste listed on this Manifest. The address must be the site address, which may differ from the company mailing address.

Item 10. U.S. EPA ID Number

Enter the U.S. EPA twelve digit identification number of the designated facility identified in item 9.

Item 11. DOT Description [Including Proper Shipping Name, Hazard Class, and ID Number (UN/NA)]

Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste as identified in 49 CFR 171 through 177.

Note.-If additional space is needed for waste descriptions, enter these additional descriptions in item 28 on the Continuation Sheet (EPA Form 8700-22A).

Item 12. Containers (No. and Type)

Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.

Table I - Types of Containers

DM = Metal drums, barrels, kegs	CY = Cylinders
DW = Wooden drums, barrels, kegs	CM = Metal boxes, cartons, cases
DF = Fiberboard or plastic drums, barrels, kegs	(including roll-offs)
TP = Tanks portable	CW = Wooden boxes, cartons, cases
TT = Cargo tanks (tank trucks)	CF = Fiber or plastic boxes, cartons, cases
TC = Tank cars	BA = Burlap, cloth, paper or plastic bags
DT = Dump truck	

Item 13. Total Quantity

Enter the total quantity of waste described on each line.

Item 14. Unit (Wt./Vol.)

Enter the appropriate abbreviation from Table II (below) for the unit of measure.

Table II - Units of Measure

G = Gallons (liquids only)	L = Liters (liquids only)
P = Pounds	K = Kilograms
T = Tons (2000 lbs)	M = Metric tons (1000 kg)
Y = Cubic yards	N = Cubic meters

Item 15. Special Handling Instructions and Additional Information

Generators may use this space to indicate special transportation, treatment, storage, or disposal information or Bill of Lading information. States may not require additional, new, or different information in this space. For international shipments, generators must

enter in this space the point of departure (City and State) for those shipments destined for treatment, storage, or disposal outside the jurisdiction of the United States.

Item 16. Generator's Certification

The generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below. If another mode in addition to the highway mode is used, enter the appropriate additional mode (e.g., and rail) in the space below.

Primary exporters shipping hazardous wastes to a facility located outside of the United States must add to the end of the first sentence of the certification the following words "and conforms to the terms of the EPA Acknowledgment of Consent to the shipment."

In signing the waste minimization certification statement, those generators who have not been exempted by statute or regulation from the duty to make a waste minimization certification under section 3002(b) of RCRA are also certifying that they have complied with the waste minimization requirements.

Generators may preprint the words. "On behalf of" in the signature block or may hand write this statement on the signature block prior to signing the generator certifications.

Note.-All of the above information except the handwritten signature required in item 16 may be preprinted.

TRANSPORTERS

Item 17. Transporter 1 Acknowledgement of Receipt of Materials

Enter the name of the person accepting the waste on behalf of the first transporter. That person must acknowledge acceptance of the waste described on the Manifest by signing and entering the date of receipt.

Item 18. Transporter 2 Acknowledgement of Receipt of Materials

Enter, if applicable, the name of the person accepting the waste on behalf of the second transporter. That person must acknowledge acceptance of the waste described on the Manifest by signing and entering the date of receipt.

Note.-International Shipments - Transporter Responsibilities.

Exports.-Transporters must sign and enter the date the waste left the United States in item 15 of Form 8700-22.

Imports.-Shipments of hazardous waste regulated by RCRA and transported into the United States from another country must upon entry be accompanied by the U.S. EPA Uniform Hazardous Waste Manifest. Transporters who transport hazardous waste into the United States from another country are responsible for completing the Manifest (40 CFR 263.10(c)(1)).

OWNERS AND OPERATORS OF TREATMENT, STORAGE, OR DISPOSAL FACILITIES

Item 19. Discrepancy Indication Space

The authorized representative of the designated (or alternate) facility's owner or operator must note in this space any significant discrepancy between the waste described on the Manifest and the waste actually received at the facility.

Owners and operators of facilities located in unauthorized States (i.e., the U.S. EPA administers the hazardous waste management program) who cannot resolve significant discrepancies within 15 days of receiving the waste must submit to their Regional Administrator (see list below) a letter with a copy of the Manifest at issue describing the discrepancy and attempts to reconcile it (40 CFR 264.72 and 265.72).

Owners and operators of facilities located in authorized States (i.e., those States that have received authorization from the U.S. EPA to administer the hazardous waste program) should contact their State agency for information on State Discrepancy Report requirements.

EPA Regional Administrators

Regional Administrator, U.S. EPA Region I, J.F. Kennedy Fed. Bldg., Boston, MA 02203

Regional Administrator, U.S. EPA Region II, 26 Federal Plaza, New York, NY 10278

Regional Administrator, U.S. EPA Region III, 6th and Walnut Sts., Philadelphia, PA 19106

Regional Administrator, U.S. EPA Region IV, 345 Courtland St., NE., Atlanta, GA 30365

Regional Administrator, U.S. EPA Region V, 230 S. Dearborn St., Chicago, IL 60604

Regional Administrator, U.S. EPA Region VI, 1201 Elm Street, Dallas, TX 75270

Regional Administrator, U.S. EPA Region VII, 324 East 11th Street, Kansas City, MO 64106

Regional Administrator, U.S. EPA Region VIII, 1860 Lincoln Street, Denver, CO 80295

Regional Administrator, U.S. EPA Region IX, 215 Fremont Street, San Francisco, CA 94105

Regional Administrator, U.S. EPA Region X, 1200 Sixth Avenue, Seattle, WA 98101

Item 20. Facility Owner or Operator: Certification of Receipt of Hazardous Materials Covered by This Manifest Except as Noted in Item 19

Print or type the name of the person accepting the waste on behalf of the owner or operator of the facility. That person must acknowledge acceptance of the waste described on the Manifest by signing and entering the date of receipt.

Items A-K are not required by Federal regulations for intra- or interstate transportation. However, States may require generators and owners or operators of treatment, storage, or disposal facilities to complete some or all of items A-K as part of State manifest reporting requirements. Generators and owners and operators of treatment, storage, or disposal facilities are advised to contact State officials for guidance on completing the shaded areas of the Manifest.

Emergency Contact Telephone Number

Please print or type
(Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039. Expires 9-30-99

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address USEPA REGION 5 77 W. Jackson Blvd Chicago, IL 60604 886 7182		4. Generator's US EPA ID No. OHS-FM050803800009		A. State Manifest Document Number		
5. Transporter 1 Company Name Enviroserve		6. US EPA ID Number OH D987050564		B. State Generator's ID		
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID 77160HW		
9. Designated Facility Name and Site Address EPA on Mental Protection Sues, Inc 4 Industrial Park Drive Wheeling, WV 26008		10. US EPA ID Number		D. Transporter's Phone 304-232-1590		
				E. State Transporter's ID 800-642-1311		
				F. Transporter's Phone		
				G. State Facility's ID		
				H. Facility's Phone 304 232 1590		
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers		13. Total Quantity	14. Unit Wt/Vol	15. Waste No.
a. HM RQ, Polychlorinated Biphenyls, Mixture X Class 9, PG III UN 2315		No. Type				
b. RQ, Polychlorinated Biphenyls, Mixture X Class 9, PG III UN 2315		0.01 CM		3,763 K		
c. RQ, Polychlorinated Biphenyls, Mixture X Class 9, PG III UN 2315		0.01 CM		4,727 K		
d.		0.01 CM		3,771 K		
J. Additional Descriptions for Materials Listed Above		K. Handling Codes for Wastes Listed Above				
Date taken out of service for each 8/26/00						
15. Special Handling Instructions and Additional Information						
11a. C-505415/JI-A 11b. C-503736/JI-B 11c. C-856081/JI-C						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.						
Printed/Typed Name		Signature		Month Day Year		
THOMAS COOK		TL Cook		10/19/00		
17. Transporter 1 Acknowledgement of Receipt of Materials		Printed/Typed Name		Signature		
		Mike Page		Mike Page		
18. Transporter 2 Acknowledgement of Receipt of Materials		Printed/Typed Name		Signature		
19. Discrepancy Indication Space						
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.						
Printed/Typed Name		Signature		Month Day Year		

UNIFORM HAZARDOUS WASTE MANIFEST AND INSTRUCTIONS EPA FORM 8700-22

U.S. EPA Form 8700-22

Read all instructions before completing this form.

This form has been designed for use on a 12-pitch (elite) typewriter; a firm point pen may also be used - press down hard.

Federal regulations require generators and transporters of hazardous waste and owners or operators of hazardous waste treatment, storage, and disposal facilities to use this form (8700-22) and, if necessary, the continuation sheet (Form 8700-22A) for both inter- and intrastate transportation.

Federal regulations also require generators and transporters of hazardous waste and owners or operators of hazardous waste treatment, storage and disposal facilities to complete the following information:

GENERATORS

Item 1. Generator's U.S. EPA ID Number - Manifest Document Number

Enter the generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this Manifest (e.g., 00001) by the generator.

Item 2. Page 1 of -

Enter the total number of pages used to complete this Manifest, i.e., the first page (EPA Form 8700-22) plus the number of Continuation Sheets (EPA Form 8700-22A), if any.

Item 3. Generator's Name and Mailing Address

Enter the name and mailing address of the generator. The address should be the location that will manage the returned Manifest forms.

Item 4. Generator's Phone Number

Enter a telephone number where an authorized agent of the generator may be reached in the event of an emergency.

Item 5. Transporter 1 Company Name

Enter the company name of the first transporter who will transport the waste.

Item 6. U.S. EPA ID Number

Enter the U.S. EPA twelve digit identification number of the first transporter identified in item 5.

Item 7. Transporter 2 Company Name

If applicable, enter the company name of the second transporter who will transport the waste. If more than two transporters are used to transport the waste, use a Continuation Sheet(s) (EPA Form 8700-22A) and list the transporters in the order they will be transporting the waste.

Item 8. U.S. EPA ID Number

If applicable, enter the U.S. EPA twelve digit identification number of the second transporter identified in item 7.

Note.-If more than two transporters are used, enter each additional transporter's company name and U.S. EPA twelve digit identification number in items 24-27 on the Continuation Sheet (EPA Form 8700-22A). Each Continuation Sheet has space to record two additional transporters. Every transporter used between the generator and the designated facility must be listed.

Item 9. Designated Facility Name and Site Address

Enter the company name and site address of the facility designated to receive the waste listed on this Manifest. The address must be the site address, which may differ from the company mailing address.

Item 10. U.S. EPA ID Number

Enter the U.S. EPA twelve digit identification number of the designated facility identified in item 9.

Item 11. U.S. DOT Description [Including Proper Shipping Name, Hazard Class, and ID Number (UN/NA)]

Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste as identified in 49 CFR 171 through 177.

Note.-If additional space is needed for waste descriptions, enter these additional descriptions in item 28 on the Continuation Sheet (EPA Form 8700-22A).

Item 12. Containers (No. and Type)

Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.

Table I - Types of Containers

DM = Metal drums, barrels, kegs	CY = Cylinders
DW = Wooden drums, barrels, kegs	CM = Metal boxes, cartons, cases (including roll-offs)
DF = Fiberboard or plastic drums, barrels, kegs	CW = Wooden boxes, cartons, cases
TP = Tanks portable	CF = Fiber or plastic boxes, cartons, cases
TT = Cargo tanks (tank trucks)	BA = Burlap, cloth, paper or plastic bags
TC = Tank cars	
DT = Dump truck	

Item 13. Total Quantity

Enter the total quantity of waste described on each line.

Item 14. Unit (Wt./Vol.)

Enter the appropriate abbreviation from Table II (below) for the unit of measure.

Table II - Units of Measure

G = Gallons (liquids only)	L = Liters (liquids only)
P = Pounds	K = Kilograms
T = Tons (2000 lbs)	M = Metric tons (1000 kg)
Y = Cubic yards	N = Cubic meters

Item 15. Special Handling Instructions and Additional Information

Generators may use this space to indicate special transportation, treatment, storage, or disposal information or Bill of Lading information. States may not require additional, new, or different information in this space. For international shipments, generators must

enter in this space the point of departure (City and State) for those shipments destined for treatment, storage, or disposal outside the jurisdiction of the United States.

Item 16. Generator's Certification

The generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below. If another mode in addition to the highway mode is used, enter the appropriate additional mode (e.g., and rail) in the space below.

Primary exporters shipping hazardous wastes to a facility located outside of the United States must add to the end of the first sentence of the certification the following words "and conforms to the terms of the EPA Acknowledgment of Consent to the shipment."

In signing the waste minimization certification statement, those generators who have not been exempted by statute or regulation from the duty to make a waste minimization certification under section 3002(b) of RCRA are also certifying that they have complied with the waste minimization requirements.

Generators may preprint the words, "On behalf of" in the signature block or may hand write this statement on the signature block prior to signing the generator certifications.

Note.-All of the above information except the handwritten signature required in item 16 may be preprinted.

TRANSPORTERS

Item 17. Transporter 1 Acknowledgement of Receipt of Materials

Enter the name of the person accepting the waste on behalf of the first transporter. That person must acknowledge acceptance of the waste described on the Manifest by signing and entering the date of receipt.

Item 18. Transporter 2 Acknowledgement of Receipt of Materials

Enter, if applicable, the name of the person accepting the waste on behalf of the second transporter. That person must acknowledge acceptance of the waste described on the Manifest by signing and entering the date of receipt.

Note.-International Shipments - Transporter Responsibilities.

Exports-Transporters must sign and enter the date the waste left the United States in item 15 of Form 8700-22.

Imports-Shipments of hazardous waste regulated by RCRA and transported into the United States from another country must upon entry be accompanied by the U.S. EPA Uniform Hazardous Waste Manifest. Transporters who transport hazardous waste into the United States from another country are responsible for completing the Manifest (40 CFR 263.10(c)(1)).

OWNERS AND OPERATORS OF TREATMENT, STORAGE, OR DISPOSAL FACILITIES

Item 19. Discrepancy Indication Space

The authorized representative of the designated (or alternate) facility's owner or operator must note in this space any significant discrepancy between the waste described on the Manifest and the waste actually received at the facility.

Owners and operators of facilities located in unauthorized States (i.e., the U.S. EPA administers the hazardous waste management program) who cannot resolve significant discrepancies within 15 days of receiving the waste must submit to their Regional Administrator (see list below) a letter with a copy of the Manifest at issue describing the discrepancy and attempts to reconcile it (40 CFR 264.72 and 265.72).

Owners and operators of facilities located in authorized States (i.e., those States that have received authorization from the U.S. EPA to administer the hazardous waste program) should contact their State agency for information on State Discrepancy Report requirements.

EPA Regional Administrators

Regional Administrator, U.S. EPA Region I, J.F. Kennedy Fed. Bldg., Boston, MA 02203

Regional Administrator, U.S. EPA Region II, 26 Federal Plaza, New York, NY 10278

Regional Administrator, U.S. EPA Region III, 6th and Walnut Sts., Philadelphia, PA 19106

Regional Administrator, U.S. EPA Region IV, 345 Courtland St., NE., Atlanta, GA 30365

Regional Administrator, U.S. EPA Region V, 230 S. Dearborn St., Chicago, IL 60604

Regional Administrator, U.S. EPA Region VI, 1201 Elm Street, Dallas, TX 75270

Regional Administrator, U.S. EPA Region VII, 324 East 11th Street, Kansas City, MO 64106

Regional Administrator, U.S. EPA Region VIII, 1860 Lincoln Street, Denver, CO 80295

Regional Administrator, U.S. EPA Region IX, 215 Fremont Street, San Francisco, CA 94105

Regional Administrator, U.S. EPA Region X, 1200 Sixth Avenue, Seattle, WA 98101

Item 20. Facility Owner or Operator: Certification of Receipt of Hazardous Materials Covered by This Manifest Except as Noted in Item 19

Print or type the name of the person accepting the waste on behalf of the owner or operator of the facility. That person must acknowledge acceptance of the waste described on the Manifest by signing and entering the date of receipt.

Items A-K are not required by Federal regulations for intra- or interstate transportation. However, States may require generators and owners or operators of treatment, storage, or disposal facilities to complete some or all of items A-K as part of State manifest reporting requirements. Generators and owners and operators of treatment, storage, or disposal facilities are advised to contact State officials for guidance on completing the shaded areas of the Manifest.